LOCATIONAL IDENTIFIER	Business Name	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	SERVICE LINE SIZE	INSTALL DATE	MATERIAL	ТҮРЕ	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?
1904 ANDRAYA LN		N	P	N	1"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1905 ANDRAYA LN		N N	P	N N	1" 1"	2005	P P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1912 ANDRAYA LN 1916 ANDRAYA LN		N N	P D	N N	1"	2005 2005	Р Р	SF SF	Installation record Installation record	Y	2005	Visual insp during install or repair Visual insp during install or repair	Installed after lead ban Installed after lead ban	N N
1917 ANDRAYA LN		N N	<u>Р</u>	N N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1919 ANDRAYA LN		N	P	N	1"	2005	P	SF	Installation record	· Y	2005	Visual insp during install or repair	Installed after lead ban	N
1921 ANDRAYA LN		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1923 ANDRAYA LN		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
1927 ANDRAYA LN		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
1929 ANDRAYA LN		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
1933 ANDRAYA LN		N	Р	N	1"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1935 ANDRAYA LN		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1939 ANDRAYA LN		N	P	N N	1" 1"	2005	P P	SF	Installation record	Y V	2005	Visual insp during install or repair	Installed after lead ban	N
1941 ANDRAYA LN 1945 ANDRAYA LN		N N	P	N N	1"	2005	Р Р	SF SF	Installation record Installation record	Y	2005	Visual insp during install or repair Visual insp during install or repair	Installed after lead ban Installed after lead ban	N N
1947 ANDRAYA LN		N N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1951 ANDRAYA LN		N	Р	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1953 ANDRAYA LN		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1957 ANDRAYA LN		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
1959 ANDRAYA LN		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
1963 ANDRAYA LN		N	Р	N	1"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1965 ANDRAYA LN		N	Р	N	1"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1969 ANDRAYA LN		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1971 ANDRAYA LN		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1973 ANDRAYA LN 1975 ANDRAYA LN		N N	P	N N	1" 1"	2005 2005	P P	SF SF	Installation record Installation record	Y	2005 2005	Visual insp during install or repair	Installed after lead ban Installed after lead ban	N N
1908 BONFIRE WAY		N N	<u>Р</u>	N N	1"	2003	P	SF	Installation record	Y	2003	Visual insp during install or repair Visual insp during install or repair	Installed after lead ban	N
1909 BONFIRE WAY		N N	P	N N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N N
1914 BONFIRE WAY		N	Р	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1917 BONFIRE WAY		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1922 BONFIRE WAY		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1924 ANDRAYA LN		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1925 BONFIRE WAY		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1930 BONFIRE WAY		N	P	N	1"	2004	Р	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1933 BONFIRE WAY		N	P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1936 BONFIRE WAY		N	P	N N	1"	2004	P	SF	Installation record	Y Y	2004	Visual insp during install or repair	Installed after lead ban	N N
1939 BONFIRE WAY 1943 BONFIRE WAY		N N	P D	N N	1" 1"	2004 2004	<u>Р</u> Р	SF SF	Installation record Installation record	Y v	2004	Visual insp during install or repair Visual insp during install or repair	Installed after lead ban Installed after lead ban	N N
1949 BONFIRE WAY		N N	P	N N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N N
1950 BONFIRE WAY		N	P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
2660 BOXWOOD CIR		N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2667 BOXWOOD CIR		N	Р	N	1"	2006	Р	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2670 BOXWOOD CIR		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2676 BOXWOOD CIR		N	Р	N	1"	2006	Р	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2677 BOXWOOD CIR		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2682 BOXWOOD CIR		N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2685 BOXWOOD CIR		N N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2686 BOXWOOD CIR 2689 BOXWOOD CIR		N N	P	N N	1" 1"	2006 2006	P P	SF SF	Installation record Installation record	Y	2006 2006	Visual insp during install or repair Visual insp during install or repair	Installed after lead ban Installed after lead ban	N N
2692 BOXWOOD CIR		N N	P P	N N	1"	2006	P P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2697 BOXWOOD CIR		N N	P	N N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N N
2699 BOXWOOD CIR		N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2702 BOXWOOD CIR		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2705 BOXWOOD CIR		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2708 BOXWOOD CIR		N	Р	N	1"	2006	Р	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2709 BOXWOOD CIR		N	Р	N	1"	2006	Р	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2712 BOXWOOD CIR		N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2713 BOXWOOD CIR		N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
1638 CADY LN		N	P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N N
1643 CADY LN 1646 CADY LN		N N	P	N N	1" 1"	2002 2002	P P	SF SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N N
1654 CADY LN		N N	P	N N	1"	2002	Р Р	SF SF	Installation record Installation record	Y	2002	Visual insp during install or repair Visual insp during install or repair	Installed after lead ban Installed after lead ban	N N
1655 CADY LN		N N	Р	N N	1"	2002	P P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N N
1662 CADY LN		N N	P	N N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N N
1663 CADY LN		N N	Р	N N	1"	2002	Р	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N N
1670 CADY LN		N	Р	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1671 CADY LN		N	P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N

1678 CADY LN 1679 CADY LN	N N	Р	N	1"	2002	Р	SF	Installation record	V	2002	Visual insp during install or repair	Installed after lead ban	
	N.						31	installation record	<u> </u>	2002	visual ilisp durillg ilistali ol Tepali	mistalieu arter leau ban	N
	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1686 CADY LN	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1694 CADY LN	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1702 CADY LN	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1707 CADY LN	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1710 CADY LN	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1718 CADY LN	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1719 CADY LN	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1727 CADY LN	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1730 CADY LN	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1735 CADY LN	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1743 CADY LN	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1750 CADY LN	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1755 CADY LN	N	Р	N	1"	2002	P	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1767 CADY LN	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1770 CADY LN	N	P	N	1"	2002	P	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1779 CADY LN	N	P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1780 CADY LN	N N	<u>.</u> Р	N	1"	2002	D	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
901 CHELSEA CT	N N	Р	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
904 CHELSEA CT	N N	P	N	1"	2002	P	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
907 CHELSEA CT	N N	P	N	1"	2002	P P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
912 CHELSEA CT	N N	P	N	1"	2002	<u>Р</u>	SF	Installation record	V	2002	Visual insp during install or repair	Installed after lead ban	N
915 CHELSEA CT	N N	P P	N N	1"	2002	Р Р	SF SF		Y	2002	Visual insp during install or repair  Visual insp during install or repair		N N
920 CHELSEA CT	N N	P	N N	1"	2002	<u>Р</u>	SF SF	Installation record	Y	2002		Installed after lead ban	N N
		P				P		Installation record	Y		Visual insp during install or repair	Installed after lead ban	
921 CHELSEA CT	N	· · · · · · · · · · · · · · · · · · ·	N	1"	2002	Ρ	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
929 CHELSEA CT	N	P	N	1"	2002	Ρ	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
2313 CLEM LN	N	<u>'</u>	N	1"	2007	P	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	N
2316 CLEM LN	N	P	N	1"	2007	P	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2331 CLEM LN	N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2343 CLEM LN	N	Р	N	1"	2007	Р	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	N
2344 CLEM LN	N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2353 CLEM LN	N	P	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2354 CLEM LN	N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
1430 CRABB CT	N	Р	N	1"	1992	Р	SF	Installation record	Υ	1992	Visual insp during install or repair	Installed after lead ban	N
1438 CRABB CT	N	Р	N	1"	1992	Р	SF	Installation record	Υ	1992	Visual insp during install or repair	Installed after lead ban	N
1458 CRABB CT	N	Р	N	1"	1992	Р	SF	Installation record	Υ	1992	Visual insp during install or repair	Installed after lead ban	N
1648 CRIMSON CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1653 CRIMSON CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1654 CRIMSON CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1663 CRIMSON CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1664 CRIMSON CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1670 CRIMSON CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1673 CRIMSON CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1676 CRIMSON CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1686 CRIMSON CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1694 CRIMSON CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1704 CRIMSON CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1712 CRIMSON CT	N N	P	N	1"	1995	<u>Р</u>	SF	Installation record	Y	1995	Visual insp during install or repair	Installed after lead ban	N
1720 CRIMSON CT	N N	Р	N	1"	1995	P	SF	Installation record	Y	1995	Visual insp during install or repair	Installed after lead ban	N
1728 CRIMSON CT	N N	P	N	1"	1995	P	SF	Installation record	Y	1995	Visual insp during install or repair	Installed after lead ban	N
1731 CRIMSON CT	N N	P	N	1"	1995	P	SF	Installation record	Y	1995	Visual insp during install or repair	Installed after lead ban	N
1736 CRIMSON CT	N N	P P	N	1"	1995	P P	SF	Installation record	٧	1995	Visual insp during install or repair	Installed after lead ban	N
1746 CRIMSON CT	N N	<u>Р</u>	N N	1"	1995	P P	SF	Installation record	Y	1995	Visual insp during install or repair  Visual insp during install or repair	Installed after lead ban	N
1758 CRIMSON CT	N N	P	N	1"	1995	P P	SF	Installation record	Y	1995	Visual insp during install or repair  Visual insp during install or repair	Installed after lead ban	N
1770 CRIMSON CT	N N	P P	N	1"	1995	P	SF		Y	1995		Installed after lead ban	N
	N N	P P				P P	SF SF	Installation record	Y		Visual insp during install or repair		
1775 CRIMSON CT		P	N	1"	1995			Installation record	<u> </u>	1995	Visual insp during install or repair	Installed after lead ban	N
1932 CRIMSON WAY	N	•	N	1"	2002	P	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1940 CRIMSON WAY	N	P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1945 CRIMSON WAY	N	P	N	1"	2002	Р	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1948 CRIMSON WAY	N	P	N	1"	2002	P	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1956 CRIMSON WAY	N	P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1957 CRIMSON WAY	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1964 CRIMSON WAY	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1972 CRIMSON WAY	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1980 CRIMSON WAY	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1983 CRIMSON WAY	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1991 CRIMSON WAY	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1998 CRIMSON WAY	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1999 CRIMSON WAY	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
2008 CRIMSON WAY	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
			N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N

2016 CRIMSON WAY		N	P	N N	1"	2002	P	SF	Installation record	Υ Υ	2002	Visual insp during install or repair	Installed after lead ban	N
2024 CRIMSON WAY	DADIC DI ACE EIGENI IOMED LIOI DINOCALI C	N	Р	N	1"	2002	P	SF NONRES	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1674 EISENHOWER RD	PARK PLACE EISENHOWER HOLDINGS LLC	N N	P D	N N	10" 6"	1997 1997	P P	NONRES	Installation record	Y	1997 1997	Visual insp during install or repair	Installed after lead ban	N N
1686 EISENHOWER RD 1708 EISENHOWER RD	PREVEA CLINIC-LAW ROBINSON INC	N	P D	N N	1"	1997	P	NONRES	Installation record Installation record	Y	1997	Visual insp during install or repair Visual insp during install or repair	Installed after lead ban Installed after lead ban	N N
1740 EISENHOWER RD	ROBINSON INC	N	Р 	N	10"	1997	P	NONRES	Installation record	Y	1997	Visual insp during install or repair	Installed after lead ban	N N
1740 EISENHOWER RD #B	ROBINSON INC	N	D D	N	10"	1997	P	NONRES	Installation record	Y	1997	Visual insp during install or repair	Installed after lead ban	N
1837 EISENHOWER RD	PACKERLAND TAPE	N	p p	N	1"	1999	Р	NONRES	Installation record	Y	1999	Visual insp during install or repair	Installed after lead ban	N N
2125 FRENCH RD	QUALITY TRUCK	N	P	N	8"	2005	P	NONRES	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1521 GOLDEN MOON CT	QONEITT TROOK	N	P	N	1"	2003	P	SF	Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	N
1524 GOLDEN MOON CT		N	P	N	1"	2003	P	SF	Installation record	Υ Υ	2003	Visual insp during install or repair	Installed after lead ban	N
1532 GOLDEN MOON CT		N	P	N	1"	2003	Р	SF	Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	N
1537 GOLDEN MOON CT		N	 P	N	1"	2003	P	SF	Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	N
1542 GOLDEN MOON CT		N	P	N	1"	2003	Р	SF	Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	N
1555 GOLDEN MOON CT		N	P	N	1"	2003	P	SF	Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	N
1585 GRANADA CT		N	P	N	1"	1998	P	SF	Installation record	Y	1998	Visual insp during install or repair	Installed after lead ban	N
1586 GRANADA CT		N	P	N	1"	1998	P	SF	Installation record	Y	1998	Visual insp during install or repair	Installed after lead ban	N
1594 GRANADA CT		N	P	N	1"	1998	Р	SF	Installation record	Y	1998	Visual insp during install or repair	Installed after lead ban	N
1595 GRANADA CT		N	P	N	1"	1998	P	SF	Installation record	Y	1998	Visual insp during install or repair	Installed after lead ban	N
1602 GRANADA CT		N	P	N	1"	1998	Р	SF	Installation record	Y	1998	Visual insp during install or repair	Installed after lead ban	N
1603 GRANADA CT		N	P	N	1"	1998	P	SF	Installation record	Y	1998	Visual insp during install or repair	Installed after lead ban	N
1605 GRANADA CT		N	Р	N	1"	1998	Р	SF	Installation record	Υ	1998	Visual insp during install or repair	Installed after lead ban	N
1388 GRANT ST		N	Р	N	1"	1993	P	SF	Installation record	Y	1993	Visual insp during install or repair	Installed after lead ban	N
1400 GRANT ST		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1418 GRANT ST		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1426 GRANT ST		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1434 GRANT ST		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1454 GRANT ST		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1455 GRANT ST		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1470 GRANT ST		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1488 GRANT ST		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1503 GRANT ST		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1508 GRANT ST		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1527 GRANT ST	OAKS FAMILY CARE CENTER	N	Р	N	1"	1993	Р	OTH	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1558 GRANT ST		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1561 GRANT ST		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1574 GRANT ST		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1581 GRANT ST		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1592 GRANT ST		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1593 GRANT ST		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1781 GRANT ST	AG PROPERTIES LLC	N	Р	N	8"	2002	Р	MF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1783 GRANT ST	AG PROPERTIES LLC	N	Р	N	8"	2002	Р	MF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1785 GRANT ST	AG PROPERTIES LLC	N	Р	N	8"	2002	Р	MF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1787 GRANT ST	AG PROPERTIES LLC	N	Р	N	8"	2002	Р	MF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1789 GRANT ST	AG PROPERTIES LLC	N	Р	N	8"	2002	Р	MF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1791 GRANT ST	AG PROPERTIES LLC	N	Р	N	8"	2002	Р	MF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1793 GRANT ST	AG PROPERTIES LLC	N	Р	N	8"	2002	Р	MF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1795 GRANT ST	AG PROPERTIES LLC	N	Р	N	8"	2002	Р	MF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1879 GRANT ST		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1798 GRANT STREET	JOURNEY CHURCH PARSONAGE	N	Р	N	1"	2022	Р	SF	Installation record	Υ	2022	Visual insp during install or repair	Installed after lead ban	N
1800 GRANT STREET	JOURNEY COMMUNITY CHURCH, INC	N	Р	N	8"	2019	P	NONRES	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
1939 GRANT STREET		N	Р	N	1"	1993	Р	SF	Installation record	Y	1993	Visual insp during install or repair	Installed after lead ban	N
1325 QUARRY PARK DR	SCOTT'S SUBS_INC.	N	Р	N	1"	2005	Р	NONRES	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
1303 GRASS WOODS CT		N	Р	N	1"	2003	Р	SF	Installation record	Υ	2003	Visual insp during install or repair	Installed after lead ban	N
1304 GRASS WOODS CT		N	Р	N	1"	2003	P	SF	Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	N
1311 GRASS WOODS CT		N	Р	N	1"	2003	Р	SF	Installation record	Υ	2003	Visual insp during install or repair	Installed after lead ban	N
1312 GRASS WOODS CT		N	P	N	1"	2003	Р	SF	Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	N
1317 GRASS WOODS CT		N	Р	N	1"	2003	Р	SF	Installation record	Υ	2003	Visual insp during install or repair	Installed after lead ban	N
924 GREEN RIDGE DR		N	Р	N	1"	2015	P	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
916 GREEN RIDGE DR		N	Р	N	1"	2015	Р	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
908 GREEN RIDGE DR		N	P	N	1"	2015	P	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
900 GREEN RIDGE DR		N	P	N	1"	2015	P	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
901 GREEN RIDGE DR		N	Р	N	1"	2015	P	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
907 GREEN RIDGE DR		N	Р	N	1"	2015	P	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
915 GREEN RIDGE DR		N	Р	N	1"	2015	P	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
923 GREEN RIDGE DR		N	Р	N	1"	2015	Р	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
931 GREEN RIDGE DR		N	Р	N	1"	2015	P	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
932 GREEN RIDGE DR		N	Р	N	1"	2004	P	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
940 GREEN RIDGE DR		N	P	N	1"	2004	Р	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
948 GREEN RIDGE DR		N	P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
		N 1	D	N	1"	2004	P	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
949 GREEN RIDGE DR 956 GREEN RIDGE DR		N N	P P	N	1"	2004	Р	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N

957 GREEN RIDGE DR		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
964 GREEN RIDGE DR		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
965 GREEN RIDGE DR		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
972 GREEN RIDGE DR		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
977 GREEN RIDGE DR		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
980 GREEN RIDGE DR		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
707 GRYFFINDOR CT		N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
714 GRYFFINDOR CT		N	P	N	1"	2006	<u>.</u> Р	SF	Installation record	· v	2006	Visual insp during install or repair	Installed after lead ban	N
708 GRYFFINDOR CT		N	P	N	1"	2006	D	SF	Installation record	V	2006	Visual insp during install or repair	Installed after lead ban	N
1030 HOKS RIDGE LN		N	P P	N	1"	2002	P P	SF	Installation record		2002	Visual insp during install or repair	Installed after lead ban	N
1030 HOKS RIDGE LN		N	P P	N	1"	2002	n n	SF		ı v	2002	1 0 1		
			<u> </u>				P P		Installation record	Y		Visual insp during install or repair	Installed after lead ban	N
1038 HOKS RIDGE LN		N	P	N	1"	2002	P	SF	Installation record		2002	Visual insp during install or repair	Installed after lead ban	N
1046 HOKS RIDGE LN		N	Р	N	1"	2002	Р	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1051 HOKS RIDGE LN		N	Р	N	1"	2002	Р	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1054 HOKS RIDGE LN		N	Р	N	1"	2002	Р	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1078 HOKS RIDGE LN		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1085 HOKS RIDGE LN		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1086 HOKS RIDGE LN		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1093 HOKS RIDGE LN		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1094 HOKS RIDGE LN		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1101 HOKS RIDGE LN		N	Р	N	1"	2002	Р	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1102 HOKS RIDGE LN		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1108 HOKS RIDGE LN		N	P	N	1"	2002	P	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1426 HONOR WAY		N	P	N	1"	2005	<u>.</u> Р	SF	Installation record	Υ Υ	2005	Visual insp during install or repair	Installed after lead ban	N
1427 HONOR WAY		N	P	N	1"	2005	D P	SF	Installation record	Υ Υ	2005	Visual insp during install or repair	Installed after lead ban	N
1432 HONOR WAY		N	P P	N	1"	2005	P P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
		N	P P				D P			1 V				
1433 HONOR WAY			<u> </u>	N	1"	2005	'	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1438 HONOR WAY		N	P	N	1"	2005	P	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
1439 HONOR WAY		N	Р	N	1"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1442 HONOR WAY		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
1443 HONOR WAY		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
1448 HONOR WAY		N	Р	N	1"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1451 HONOR WAY		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
1454 HONOR WAY		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
1457 HONOR WAY		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
1460 HONOR WAY		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
1466 HONOR WAY		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
2685 LACEWOOD LN		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2695 LACEWOOD LN		N	P	N	1"	2006	P	SF	Installation record	Υ Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2699 LACEWOOD LN		N	Р	N	1"	2006	Р	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2514 LAWRENCE DR		N	P	N	1"	2005	D	SF	Installation record	Y	2005		Installed after lead ban	N
		N	P P	N	1"		P P	SF SF		ı V		Visual insp during install or repair		N
2534 LAWRENCE DR			·	• •	<u>-</u>	2005	P P		Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	• •
2540 LAWRENCE DR		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
2554 LAWRENCE DR		N	P	N	1"	2005	P	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
2574 LAWRENCE DR		N	P	N	1"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
2587 LAWRENCE DR		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
2610 LAWRENCE DR		N	Р	N	1"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
2626 LAWRENCE DR		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
2638 LAWRENCE DR		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
2673 LAWRENCE DR		N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2679 LAWRENCE DR		N	Р	N	1"	2019	Р	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2685 LAWRENCE DR		N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2691 LAWRENCE DR		N	Р	N	1"	2019	Р	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2697 LAWRENCE DR		N	P	N	1"	2019	P	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2702 LAWRENCE DR		N	P	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2442 LITTLE RAPIDS RD		N	P	N	2"	2020	P	NONRES	Installation record	Y	2020	Visual insp during install or repair	Installed after lead ban	N
2434 LITTLE RAPIDS ROAD	TOWN OF LAWRENCE	N	P	N	1"	2020	P P	NONRES	Installation record	٧	2020	Visual insp during install or repair	Installed after lead ban	N
2400 SHADY COURT		N	P P	N	1 1/2"		P P			Y				
	TOWN OF LAWRENCE PURILG WORKS SHOP		· · · · · · · · · · · · · · · · · · ·			2020		NONRES	Installation record	•	2020	Visual insp during install or repair	Installed after lead ban	N
2450 SHADY COURT	TOWN OF LAWRENCE -PUBLIC WORKS SHOP	N	P	N	1"	2020	P	NONRES	Installation record	Y	2020	Visual insp during install or repair	Installed after lead ban	N N
2595 FRENCH ROAD	LAWRENCE FIRE STATION	N	P	N	2"	2020	P	NONRES	Installation record	Y	2020	Visual insp during install or repair	Installed after lead ban	N
2271 LOST DAUPHIN RD	1101105	N	P	N	1"	2007	P	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	N
2271 LOST DAUPHIN RD POOL	HOUSE	N	P	N	1"	2021	P	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
2281 LOST DAUPHIN RD		N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2295 LOST DAUPHIN RD		N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2303 LOST DAUPHIN RD		N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2303 LOST DAUPHIN RD POOL	HOUSE	N	Р	N	1"	2021	Р	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
2325 LOST DAUPHIN RD		N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2333 LOST DAUPHIN RD		N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2341 LOST DAUPHIN RD		N	P	N	1"	2007	P	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	N
2345 LOST DAUPHIN RD		N	P	N	1"	2007	P	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	N
2351 LOST DAUPHIN RD		N	P	N	1"	2007	P	SF	Installation record	Υ Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2355 LOST DAUPHIN RD		N	P	N	1"	2007	P	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	N
2000 2001 Dittol lille Ito				N	_	2007	'	31	motunation record	•	2007	. Isaar map aaring matan or repair	motanea arter lead ball	IN .

2264 LOCT DALIDLIN DD	N	P	NI NI	1"	2007	D	CE	Installation record	V	2007	Vicual inco during install or roppir	Installed ofter lead bear	N
2361 LOST DAUPHIN RD 2463 LOST DAUPHIN RD	N N	P P	N N	1" 1"	2007	P P	SF SF	Installation record Installation record	Y Y	2007	Visual insp during install or repair Visual insp during install or repair	Installed after lead ban Installed after lead ban	N N
2369 LOST DAUPHIN RD	N	P	N	1"	2007	P	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	N N
2387 LOST DAUPHIN RD	N	P	N	1"	2007	Р	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	N
2451 LOST DAUPHIN RD	N	P	N	1"	2007	P	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	N
2481 LOST DAUPHIN RD	N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2487 LOST DAUPHIN RD	N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2491 LOST DAUPHIN RD	N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2511 LOST DAUPHIN RD	N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
337 RIVERS RUN	N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
2559 LOST DAUPHIN RD	N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2571 LOST DAUPHIN RD	N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2577 LOST DAUPHIN RD	N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2595 LOST DAUPHIN RD	N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2601 LOST DAUPHIN RD	N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2607 LOST DAUPHIN RD	N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2617 LOST DAUPHIN RD	N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
2110 MAHOGANY CT	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2115 MAHOGANY CT	N	Р	N	1"	2006	P	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2116 MAHOGANY CT	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2119 MAHOGANY CT	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2120 MAHOGANY CT	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2124 MAHOGANY CT	N	P	N	1"	2006	Р	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2125 MAHOGANY CT	N	P	N	1"	2006	P	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2128 MAHOGANY CT	N	P	N	1"	2006	P	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2132 MAHOGANY CT	N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2140 MAHOGANY CT	N N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2146 MAHOGANY TRL	N	P	N	1"	2006	P	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2149 MAHOGANY TRL	N N	P	N	1"	2006	P -	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2150 MAHOGANY TRL	N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2151 MAHOGANY TRL	N N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2154 MAHOGANY TRL	N	P P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2155 MAHOGANY TRL	N N	P P	N N	1" 1"	2006	Р Р	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2157 MAHOGANY TRL		P		1"	2006	<u>Р</u>	SF SF	Installation record	•	2006	Visual insp during install or repair	Installed after lead ban	N
2158 MAHOGANY TRL	N N	P P	N N		2006 2006	P P	SF SF	Installation record	Υ	2006 2006	Visual insp during install or repair	Installed after lead ban	N N
2162 MAHOGANY TRL 2168 MAHOGANY TRL	N N	P	N N	1" 1"	2006	P P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban Installed after lead ban	N
2172 MAHOGANY TRL	N N	P	N N	1"	2006	<u>Р</u>	SF	Installation record	Y	2006	Visual insp during install or repair Visual insp during install or repair	Installed after lead ban	N N
2180 MAHOGANY TRL	N	P P	N	1"	2006	<u>Р</u> р	SF	Installation record Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2193 MAHOGANY TRL	N N	P	N N	1"	2006	P P	SF	Installation record	V	2006	Visual insp during install or repair	Installed after lead ban	N N
2200 MAHOGANY TRL	N	P	N N	1"	2006	P D	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2201 MAHOGANY TRL	N	<u>г</u>	N N	1"	2006	г D	SE SE	Installation record		2006	Visual insp during install or repair	Installed after lead ban	N
2204 MAHOGANY TRL	N	D D	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N N
2205 MAHOGANY TRL	N N	P	N	1"	2006	Р	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2208 MAHOGANY TRL	N N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2209 MAHOGANY TRL	N	P	N	1"	2006	Р	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2207 MAHOGANY TRL	N N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2212 MAHOGANY TRL	N N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2213 MAHOGANY TRL	N	P	N	1"	2006	Р	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2215 MAHOGANY TRL	N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
803 MAHOGANY CIRCLE	N	P	N	1"	2016	P	SF	Installation record	Y	2016	Visual insp during install or repair	Installed after lead ban	N
805 MAHOGANY CIRCLE	N	P	N	1"	2016	Р	SF	Installation record	Y	2016	Visual insp during install or repair	Installed after lead ban	N
809 MAHOGANY CI	N	P	N	1"	2016	P	SF	Installation record	Y	2016	Visual insp during install or repair	Installed after lead ban	N
811 MAHOGANY CI	N	Р	N	1"	2016	Р	SF	Installation record	Υ	2016	Visual insp during install or repair	Installed after lead ban	N
814 MAHOGANY CIRCLE	N	Р	N	1"	2016	Р	SF	Installation record	Υ	2016	Visual insp during install or repair	Installed after lead ban	N
815 MAHOGANY CI	N	Р	N	1"	2016	Р	SF	Installation record	Υ	2016	Visual insp during install or repair	Installed after lead ban	N
2216 MAHOGANY TRL	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
819 MAHOGANY CI	N	Р	N	1"	2016	Р	SF	Installation record	Υ	2016	Visual insp during install or repair	Installed after lead ban	N
826 MAHOHANY CI	N	Р	N	1"	2016	Р	SF	Installation record	Υ	2016	Visual insp during install or repair	Installed after lead ban	N
831 MAHOGANY CI	N	Р	N	1"	2016	Р	SF	Installation record	Υ	2016	Visual insp during install or repair	Installed after lead ban	N
338 MAHOGANY CI	N	Р	N	1"	2016	Р	SF	Installation record	Υ	2016	Visual insp during install or repair	Installed after lead ban	N
335 MAHOGANY CI	N	Р	N	1"	2016	Р	SF	Installation record	Υ	2016	Visual insp during install or repair	Installed after lead ban	N
339 MAHOGANY CI	N	Р	N	1"	2016	Р	SF	Installation record	Υ	2016	Visual insp during install or repair	Installed after lead ban	N
843 MAHOGANY CI	N	Р	N	1"	2016	Р	SF	Installation record	Υ	2016	Visual insp during install or repair	Installed after lead ban	N
847 MAHOGANY TRL	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
851 MAHOGANY CI	N	Р	N	1"	2016	Р	SF	Installation record	Υ	2016	Visual insp during install or repair	Installed after lead ban	N
2220 MAHOGANY TRL	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
B55 MAHOGANY CIRCLE	N	Р	N	1"	2016	Р	SF	Installation record	Υ	2016	Visual insp during install or repair	Installed after lead ban	N
B57 MAHOGANY CIRCLE	N	Р	N	1"	2016	Р	SF	Installation record	Υ	2016	Visual insp during install or repair	Installed after lead ban	N
OOOO MAALIOOANY TRI	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2223 MAHOGANY TRL						_				2006			NI.
2223 MAHOGANY TRL 2225 MAHOGANY TRL	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N

Second Content															
Marches   Marc	821 MAHOGANY CI		N	Р	N	1"	2016	P	SF	Installation record	Υ		Visual insp during install or repair	Installed after lead ban	N
Production	2227 MAHOGANY TRL		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
Column   C	825 MAHOGANY CI		N	Р	N	1"	2016	Р	SF	Installation record	Υ	2016	Visual insp during install or repair	Installed after lead ban	N
1989   1989	827 MAHOGANY CI		N	Р	N	1"	2016	Р	SF	Installation record	Υ	2016	Visual insp during install or repair	Installed after lead ban	N
20   10   10   10   10   10   10   10	2228 MAHOGANY TRL		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
The content of the	2229 MAHOGANY TRL		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
Part	2230 MAHOGANY TRL		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
25   26   26   27   27   28   28   28   28   28   28	2232 MAHOGANY TRL		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
230 MINOCANT TR.	2240 MAHOGANY TRL		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
25   25   25   25   25   26   27   26   27   26   27   26   27   26   27   26   27   26   27   26   27   26   27   26   27   27	2241 MAHOGANY TRL		N	Р	N	1"		Р	SF		Υ		· • ·		N
2009 MINORANT   1			N	P	N			P			Y				N
Second Process   19				D				P			V		· · · · · · · · · · · · · · · · · · ·		N
Second				D				•			-				N
Manual Content				D D							·		· • ·		N
200 MANDALP TRAIL				P D											
Manufactor   Man				Ρ							<u> </u>		· • ·		N
Methodophory Fract				Р .											N
March   Marc				Р							·		· · · · · · · · · · · · · · · · · · ·		N
297 MANUAL PORT   1987   198				Р				•			-		Visual insp during install or repair		N
19. MIT MAY MAY FOR   19. MAY   2				Р				P			<u> </u>		Visual insp during install or repair	Installed after lead ban	N
PART NOT   PART   PAR	2271 MAHOGANY TRL		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2 CM MANUALY CIRC   Manual M	1180 MID VALLEY DR	U-HAUL OF WISCONSIN	N	Р	N	10"	2007	Р	NONRES	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
	1210 MID VALLEY DR	NAPA	N	Р	N	1"	2007	Р	NONRES	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
MAN ON ALEP CF	1250 MID VALLEY DR	PAPER TRANSPORT INC	N	Р	N	8"	1992	Р	NONRES	Installation record	Υ	1992	Visual insp during install or repair	Installed after lead ban	N
NAME   NAME   N.   P	1272 MID VALLEY DR		N	Р	N	1"	1992	Р	SF	Installation record	Υ	1992	Visual insp during install or repair	Installed after lead ban	N
1998 MON MALEY DR.   N.   P.   N.   2"   1992   P.   39   1999	1284 MID VALLEY CT		N	P	N	1"		Р	SF	Installation record	Υ		Visual insp during install or repair	Installed after lead ban	N
Second Column   Second Colum			N	Р	N			Р			Υ		i ë i		N
SEAR BILLY PRINCE   SEAR PRINCIPATION   N   P   N   1°   2000   P   NORMES   Includition record   Y   2000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included after one base   No. 1000   Vanish regular stand or repair   Included aft		A & .I MOBILITY	N	P	**										N
SMANDAL  FORM   AAR SANTATON   N   P   N   1'   2000   P   NOMES   Institution record   Y   2000   Votal imp during stocked profile or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed after ceed ben   100   Votal imp during stocked or regard   Installed				D							<u> </u>				N
1924 BOYALLEY FRUCK   N   P   N   1°   2000   P   NOMES   Insulation record   Y   2000   Visual improving based or regaint   Insulative after level from   1936 BOYALLEY OR RO				D							<u> </u>				N
1854 MOVALEY OR				P D				· · · · · · · · · · · · · · · · · · ·			<u>.</u>		· • • • • • • • • • • • • • • • • • • •		N
1988 NO NALEY DR F0				P P				-			-				
172 MOVALEY OR   BOB CAT OF CREENSAY   N   P   N   1'   2000   P   NOMES   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain   Installation record   Y   2000   Vocal rate poduring relator or regain				Р							<u> </u>		· • ·		N
MANUALEY OR   GAMENE STORMSONGS   N   P   N   1"   2000   P   NOMES   Installation record   Y   2000   Vegal imposition repier   Installated after ead ben   1808 NOVALEY OR   VALEY OR				Р											N
140 MO VALLEY DR   LUMBER LUMINORMY   N   P   N   1º   2000   P   MONRES   Installation record   Y   2000   Visual region fail or region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º   2º   2000   Visual region fail in region   Installed after lead ben   1º				Р							·		· • ·		N
145 MIN VALLEY DR	1410 MID VALLEY DR	GRANITE STONEWORKS		Р	N			Р		Installation record			Visual insp during install or repair	Installed after lead ban	N
MAY ALLEY DN   VALLEY NO   VALLEY NO   VALLEY NO   VALLEY NO   VALLEY NO   VALLEY NO DEL CREY C'HINDYNACTIC   N   P   N   1°   2000   P   NOMES   Installation neered   V   2000   Visual ingo during install or repair   Installed after lead but   Valley Del Company   Valley Del Com	1450 MID VALLEY DR		N	Р	N			P	NONRES	Installation record	Y	2000	Visual insp during install or repair	Installed after lead ban	N
MAS BILLY ALLEY OR   CARGERIA NINESTRATISLIC   N   P   N   1	1452 MID VALLEY DR	LUMBER LIQUIDATORS INCORP	N	Р	N		2000	Р	NONRES	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
1484 MIN VALLEY RD	1472 MID VALLEY DR	VALLEY UNIT STEP	N	Р	N	1"	2000	Р	NONRES	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
1484 MIN VALLEY OR   CONCRESTONE MORTGAGGE   N   P   N   1°   2000   P   NORRES   Incidiation record   V   2000   Visual importung instal or repair   Installed after lead than   109 MIN VALLEY OR   COMPONENT   Intelligence   V   2000   Visual importung instal or repair   Installed after lead than   109 MIN VALLEY OR   COMPONENT   Intelligence   V   2000   Visual importung instal or repair   Installed after lead than   109 MIN VALLEY OR   COMPONENT   Intelligence   V   2000   Visual importung instal or repair   Installed after lead than   109 MIN VALLEY OR   COMPONENT   Intelligence   V   2000   Visual importung instal or repair   Installed after lead than   109 MIN VALLEY OR   CULCION   N   P   N   1°   2000   P   NORRES   Installation record   V   2000   Visual importung instal or repair   Installed after lead than   109 MIN VALLEY OR   CULCION   N   P   N   1°   2000   P   NORRES   Installation record   V   2000   Visual importung instal or repair   Installed after lead than   109 MIN VALLEY OR   CULCION   Visual importung instal or repair   Installed after lead than   100 MIN VALLEY OR   Visual importung instal or repair   Installed after lead than   100 MIN VALLEY OR   Visual importung instal or repair   Installed after lead than   100 MIN VALLEY OR   Visual importung instal or repair   Installed after lead than   100 MIN VALLEY OR   Visual importung instal or repair   Installed after lead than   100 MIN VALLEY OR   Visual importung instal or repair   Installed after lead than   100 MIN VALLEY OR   Visual importung instal or repair   Installed after lead than   100 MIN VALLEY OR   Visual importung instal or repair   Installed after lead than   100 MIN VALLEY OR   Visual importung instal or repair   Installed after lead than   100 MIN VALLEY OR   Visual importung instal or repair   Installed after lead than   100 MIN VALLEY OR   Visual importung instal or repair   Installed after lead than   100 MIN VALLEY OR   Visual importung instal or repair   Installed after lead than   100 MIN VALLEY OR   Visual impor	1482 MID VALLEY DR	CRABBKIN INVESTMENTS LLC	N	Р	N	1"	2000	Р	NONRES	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
1516 MI VALLEY OR   AP2 DEVELOPMENT LLC   N   P   N   1"   2000   P   NONRS   Installation record   Y   2000   Vasual ring during metal or repair   Installated face feed ban	1488 MID VALLEY RD	DELOREY CHIROPRACTIC	N	Р	N	1"	2000	Р	NONRES	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
19.54 MIN_VALLEY DR	1494 MID VALLEY DR	CORNERSTONE MORTGAGE	N	Р	N	1"	2000	Р	NONRES	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
1595 MID VALLEY OR	1510 MID VALLEY DR	AP2 DEVELOPMENT LLC	N	Р	N	1"	2000	Р	NONRES	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
1555 MIO VALLEY OR   COMPORT CONTROLS   N   P   N   1"   2000   P   NONNES   Installation record   Y   2000   Visual ingo during install or repair   Installed after lead ban   1555 MIO VALLEY OR   CELLCOM   N   P   N   2"   2000   P   NONNES   Installation record   Y   2000   Visual ingo during install or repair   Installed after lead ban   1555 MIO VALLEY OR   PLANK ROAD PUIS & GRILL   N   P   N   1"   2000   P   NONNES   Installation record   Y   2000   Visual ingo during install or repair   Installed after lead ban   1555 MIO VALLEY OR   PLANK ROAD PUIS & GRILL   N   P   N   1 1/2"   2019   P   NONNES   Installation record   Y   2010   Visual ingo during install or repair   Installed after lead ban   1555 MIO VALLEY OR UNITE   STATE PURPLY NOTH   TO NONNES   Installation record   Y   2010   Visual ingo during install or repair   Installed after lead ban   1555 MIO VALLEY OR SUITE   VISUAL PURPLY NOTH   TO NONNES   Installation record   Y   2019   Visual ingo during install or repair   Installed after lead ban   1555 MIO VALLEY OR SUITE   VISUAL PURPLY NOTH   TO NONNES   Installation record   Y   2019   Visual ingo during install or repair   Installed after lead ban   1555 MIO VALLEY OR SUITE   VISUAL PURPLY NOTH   TO NONNES   Installation record   Y   2019   Visual ingo during install or repair   Installed after lead ban   1555 MIO VALLEY OR A   TO NONNES   TO NONNES   Installation record   Y   2019   Visual ingo during install or repair   Installed after lead ban   1555 MIO VALLEY OR A   TO NONNES   TO NONNES   Installation record   Y   2019   Visual ingo during install or repair   Installed after lead ban   1555 MIO VALLEY OR A   TO NONNES   TO NONNES   Installation record   Y   2019   Visual ingo during install or repair   Installed after lead ban   1555 MIO VALLEY OR A   TO NONNES   TO NONNES   Installation record   Y   2019   Visual ingo during install or repair   Installed after lead ban   1555 MIO VALLEY OR A   TO NONNES   TO NONNES   Installation record   Y   2019   Visual ingo during install or re	1534 MID VALLEY DR	LANDWEHR. TIM-FLY FISHING	N	Р	N	1"	2000	Р	NONRES	Installation record	Υ	2000		Installed after lead ban	N
1555 MIO VALLEY DR			N	P	N	1"		P			Y				N
1859 MID VALLEY DR   CELLCOM				P							Y		i ë i		N
1632 MD VALLEY DR, DIVIT C   PLANK ROAD PUB & GRILL   N   P   N   1"   2000   P   NONKES   Installation record   Y   2,000   Visual inpo during install or repair   Installed after lead ban   1808 MD VALLEY RD, UNIT C   NONKES   NONKES   Installation record   Y   2,019   Visual inpol during install or repair   Installed after lead ban   1808 MD VALLEY RD, UNIT B   REVINE NUTRITION   N   P   N   11/2"   2019   P   NONKES   Installation record   Y   2,019   Visual inpol during install or repair   Installed after lead ban   1808 MD VALLEY DR, SUITE   VINTAGE ROSE BAKERY & SANDWICH SHOP   N   11/2"   2019   P   NONKES   Installation record   Y   2,019   Visual inpol during install or repair   Installed after lead ban   1809 MD VALLEY DR, SUITE   VINTAGE ROSE BAKERY & SANDWICH SHOP   N   6"   2,088   P   NONKES   Installation record   Y   2,019   Visual inpol during install or repair   Installed after lead ban   1701 MD VALLEY DR   TOTANI AMERICA   N   P   N   6"   2,088   P   NONKES   Installation record   Y   2,088   Visual inpol during install or repair   Installed after lead ban   1809 MD VALLEY DR   MINISTER SANDWICH SHOP   N   6"   2,088   P   NONKES   Installation record   Y   2,088   Visual inpol during install or repair   Installed after lead ban   1809 MD VALLEY DR   MINISTER SANDWICH SHOP   N   2"   2,088   P   NONKES   Installation record   Y   2,088   Visual inpol during install or repair   Installed after lead ban   1809 MD VALLEY DR   MINISTER SANDWICH SHOP   N   2"   2,088   P   NONKES   Installation record   Y   2,088   Visual inpol during install or repair   Installed after lead ban   1809 MD VALLEY DR   MINISTER SANDWICH SHOP   N   6"   2,001   P   NONKES   Installation record   Y   2,018   Visual inpol during install or repair   Installed after lead ban   1809 MD VALLEY DR   MINISTER SANDWICH SHOP   N   1"   2,003   P   5"   Installation record   Y   2,001   Visual inpol during install or repair   Installed after lead ban   1809 MD VALLEY DR   N   1"   2,003   P   5"   Installation record   Y				D											N
1889 MD VALLEY RD, UNIT   MECRITY HEALTH & WELLNESS   N   P   N   11/2"   2019   P   NONRES   Installation record   Y   2019   Visual into putring itself or repair   installed after lead ban   1889 MD VALLEY RD UNIT B   SWEWN ENTITION   N   P   N   11/2"   2019   P   NONRES   Installation record   Y   2019   Visual into putring itself or repair   installed after lead ban   1898 MD VALLEY DR SULTED   VISUAL NEW PARTER INC.   N   P   N   11/2"   2019   P   NONRES   Installation record   Y   2019   Visual into putring itself or repair   installed after lead ban   1707 MD VALLEY DR SULTED   VISUAL NEW PARTER INC.   N   P   N   6°   2008   P   NONRES   Installation record   Y   2008   Visual into putring itself or repair   installed after lead ban   1707 MD VALLEY DR AL   TOTANI AMERICA   N   P   N   6°   2008   P   NONRES   Installation record   Y   2008   Visual into putring itself or repair   installed after lead ban   1708 MD VALLEY DR AL   TOTANI AMERICA   N   P   N   6°   2008   P   NONRES   Installation record   Y   2008   Visual into putring itself or repair   installed after lead ban   1708 MD VALLEY DR AL   TOTANI AMERICA   N   P   N   1"   1996   P   NONRES   Installation record   Y   1996   Visual into putring itself or repair   installed after lead ban   1708 MD VALLEY DR   AL   TOTANI AMERICA   N   P   N   1"   1996   P   NONRES   Installation record   Y   1996   Visual into putring itself or repair   installed after lead ban   1708 MD VALLEY DR   EARLY NOTION SPORTS   N   P   N   1"   1996   P   NONRES   Installation record   Y   1996   Visual into putring itself or repair   installed after lead ban   1708 MD VALLEY DR   AL   TOTANI AMERICA   N   P   N   1"   1996   P   NONRES   Installation record   Y   2001   Visual into putring itself or repair   installed after lead ban   1708 MD VALLEY DR   CARLEY DR   CAR				n n											N
1889 MID VALLEY PIG NUTIF   REVIVE NUTFIFTION   N   P   N   11/2"   2019   P   NOMES   Installation record   Y   2019   Visual insign during install or repair   Installed after lead ban   1889 MID VALLEY DR SUITE   VAN RITE & FATHER NO   N   P   N   11/2"   2019   P   NOMES   Installation record   Y   2019   Visual insign during install or repair   Installed after lead ban   1889 MID VALLEY DR SUITE   VINTAGE ROSE BAKERY & SANDWICH SHOP   N   P   N   6"   2008   P   NOMES   Installation record   Y   2019   Visual insign during install or repair   Installed after lead ban   1701 MID VALLEY DR AD   TOTANI AMERICA   N   P   N   6"   2008   P   NOMES   Installation record   Y   2008   Visual insign during install or repair   Installed after lead ban   1702 MID VALLEY DR AD   Visual inspection   V   2008   V				P D							-				N
1889 MID VALLEY OR SUITE A VAN RITE & FATHER INC				P				-			<u> </u>				
1889 MID VALLEY DR   VINTAGE ROSE BAKERY & SANDWICH SHOP   N   P   N   6"   2008   P   NONRES   Installation record   Y   2019   Visual insp during install or repair   Installed after lead ban   1701 MID VALLEY DR   A   10TANI AMERICA   N   P   N   6"   2008   P   NONRES   Installation record   Y   2008   Visual insp during install or repair   Installed after lead ban   1702 MID VALLEY DR   A   10TANI AMERICA   N   P   N   6"   2008   P   NONRES   Installation record   Y   2008   Visual insp during install or repair   Installed after lead ban   1702 MID VALLEY DR   MID STATE SUPPLY   N   P   N   1"   1996   P   NONRES   Installation record   Y   1996   Visual insp during install or repair   Installed after lead ban   1708 MID VALLEY DR   MID STATE SUPPLY   N   P   N   1"   1996   P   NONRES   Installation record   Y   1996   Visual insp during install or repair   Installed after lead ban   1708 MID VALLEY DR   EZGG LLC   N   P   N   1"   1996   P   NONRES   Installation record   Y   1996   Visual insp during install or repair   Installed after lead ban   1708 MID VALLEY DR   EZGG LLC   N   P   N   6"   2001   P   NONRES   Installation record   Y   2018   Visual insp during install or repair   Installed after lead ban   1708 MID VALLEY DR   GREEN BAY TRUCK SALES   N   P   N   1"   2003   P   NONRES   Installation record   Y   2001   Visual insp during install or repair   Installed after lead ban   1000 VALLEY DR   MGPSV LLC   N   P   N   1"   2003   P   NONRES   Installation record   Y   2003   Visual insp during install or repair   Installed after lead ban   1000 VALLEY DR   NONRES   Installation record   Y   2003   Visual insp during install or repair   Installed after lead ban   1000 VALLEY DR   N   1"   2003   P   SF   Installation record   Y   2003   Visual insp during install or repair   Installed after lead ban   1000 VALLEY DR   N   1"   2003   P   SF   Installation record   Y   2003   Visual insp during install or repair   Installed after lead ban   1000 VALLEY DR   N   1"   2003   P   SF   Installati				Р											N
1701 MID VALLEY OR				P									i ë i		N
1703 MID VALLEY DR				Р											N
1782 MID VALLEY DR   MID-STATE SUPPLY   N   P   N   1"   1996   P   NONRES   Installation record   Y   1996   Visual insp during install or repair   Installed after lead ban	-			P							·				N
1872 MID VALLEY DR M3 INSURANCE N P N 2" 2018 P NONRES Installation record Y 2018 Visual insp during install or repair Installed after lead ban 1785 MID VALLEY DR EZGB LLC N P P N 1" 1996 P NONRES Installation record Y 2001 Visual insp during install or repair Installed after lead ban 1890 MID VALLEY DR TEAM MOTOR SPORTS N P N 6" 2001 P NONRES Installation record Y 2001 Visual insp during install or repair Installed after lead ban 2090 MID VALLEY DR GREEN BAY TRUCK SALES N P N P N 8" 2001 P NONRES Installation record Y 2001 Visual insp during install or repair Installed after lead ban 112" 2023 P NONRES Installation record Y 2001 Visual insp during install or repair Installed after lead ban 112" 2023 P NONRES Installation record Y 2001 Visual insp during install or repair Installed after lead ban 2112 MID VALLEY DR GREEN BAY TRUCK SALES N P N P N 11" 2003 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 2112 MID VALLEY DR TOWER N P N 11" 2003 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 2127 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2128 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2128 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2128 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2128 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2128 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2128 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2128 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp		TOTANI AMERICA	N	Р	N			Р		Installation record	Υ		Visual insp during install or repair	Installed after lead ban	N
1785 MID VALLEY DR EZGB LLC N P N 1" 1996 P NORRES Installation record Y 1996 Visual insp during install or repair Installed after lead ban 1" 1890 MID VALLEY DR GREEN BAY TRUCK SALES N P N P N 8" 2001 P NORRES Installation record Y 2001 Visual insp during install or repair Installed after lead ban 1" 1 Installed after lead ban 1 Installed after lead ban 2 2948 MID VALLEY DR GREEN BAY TRUCK SALES N P N P N 1 1/2" 2 2023 P NORRES Installation record Y 2 2031 Visual insp during install or repair Installed after lead ban 1 Installed after lead ban 1 Installed after lead ban 1 1/2" 2 2023 P NORRES Installation record Y 2 2031 Visual insp during install or repair Installed after lead ban 1 In	1782 MID VALLEY DR	MID-STATE SUPPLY	N	Р	N	1"	1996	Р	NONRES	Installation record	Υ	1996	Visual insp during install or repair	Installed after lead ban	N
1890 MID VALLEY DR TEAM MOTOR SPORTS N P N 6" 2001 P NONRES Installation record Y 2001 Visual insp during install or repair Installed after lead ban 2240 MID VALLEY DR GREEN BAY TRUCK SALES N P N P N 11/2" 2023 P NONRES Installation record Y 2001 Visual insp during install or repair Installed after lead ban 2240 MID VALLEY DR MGPSV LC N P N 11/2" 2023 P NONRES Installation record Y 2023 Visual insp during install or repair Installed after lead ban 2112 MID VALLEY DR TOWER N P N 12" 2006 P NONRES Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1923 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1923 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1924 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1935 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1946 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1946 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1946 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1947 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1955 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1956 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1956 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1966 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or	1872 MID VALLEY DR	M3 INSURANCE	N	Р	N	2"	2018	Р	NONRES	Installation record	Υ	2018	Visual insp during install or repair	Installed after lead ban	N
2999 MID VALLEY DR GREEN BAY TRUCK SALES N P N N 8" 2001 P NONRES Installation record Y 2001 Visual insp during install or repair Installed after lead ban 2246 MID VALLEY DR MGPSV LLC N P N 1 1/2" 2023 P NONRES Installation record Y 2023 Visual insp during install or repair Installed after lead ban 2112 MID VALLEY DR TOWER N P N 1 1/2" 2003 P NONRES Installation record Y 2003 Visual insp during install or repair Installed after lead ban 212 MID VALLEY DR TOWER N P N 1 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 212 MID VALLEY DR TOWER N P N 1 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 212 MID VALLEY DR VISUAL INSTALLEY DR	1785 MID VALLEY DR	EZGB LLC	N	Р	N	1"	1996	Р	NONRES	Installation record	Υ	1996	Visual insp during install or repair	Installed after lead ban	N
2246 MID VALLEY DR MGPSV LLC N P N 11/2" 2023 P NONRES Installation record Y 2023 Visual insp during install or repair Installed after lead ban 2112 MID VALLEY DR TOWER N P N 12" 2006 P NONRES Installation record Y 2006 Visual insp during install or repair Installed after lead ban 2112 MID VALLEY DR TOWER N P N 12" 2006 P NONRES Installation record Y 2006 Visual insp during install or repair Installed after lead ban 2124 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2125 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2125 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2126 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2127 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2128 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2129 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2129 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2129 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2129 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2229 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2229 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2229 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2	1890 MID VALLEY DR	TEAM MOTOR SPORTS	N	Р	N	6"	2001	Р	NONRES	Installation record	Υ	2001	Visual insp during install or repair	Installed after lead ban	N
2246 MID VALLEY DR MGPSV LLC N P N 11/2" 2023 P NONRES Installation record Y 2023 Visual insp during install or repair Installed after lead ban 2112 MID VALLEY DR TOWER N P N 12" 2006 P NONRES Installation record Y 2006 Visual insp during install or repair Installed after lead ban 2112 MID VALLEY DR TOWER N P N 12" 2006 P NONRES Installation record Y 2006 Visual insp during install or repair Installed after lead ban 2124 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2125 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2125 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2126 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2127 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2128 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2129 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2129 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2129 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2129 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2229 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2229 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2229 MINTEN WAY N P N 11" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 2			N	Р	N			Р			Υ				N
2112 MID VALLEY DR TOWER N P N 12" 2006 P NONRES Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1924 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1925 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1935 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1935 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1936 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1946 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1947 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1956 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1956 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1966 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1968 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1964 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1965 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1965 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1965 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1965 MINTEN WAY N P N 1" 2003 P SF Installation			N	Р	N	1 1/2"		Р			Υ				N
1923 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1927 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1936 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1938 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1946 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1947 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1946 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1956 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1956 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1968 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1968 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1968 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1969 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1975 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban				P							-				N
1927 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1935 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1938 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1946 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1947 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1948 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1955 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1966 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1968 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1964 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1964 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1975 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban		· Orien		D				· · · · · · · · · · · · · · · · · · ·			<u> </u>				N
1935 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1938 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1946 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1947 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1955 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1956 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1966 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1968 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1968 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1975 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1975 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban				D											N
1938 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1946 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1947 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1955 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1956 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1963 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1964 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1964 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1975 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban				r											
1946 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1947 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1955 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1956 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1963 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1964 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1975 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1975 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban				Ρ											N
1947 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1955 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1956 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1963 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1964 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1975 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1975 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban				P				· ·							N
1955 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1956 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1963 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1964 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1975 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1975 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban				Р											N
1956 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1963 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1964 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1975 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban				Р							<u> </u>		i ë i		N
1963 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1964 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1975 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban	1955 MINTEN WAY		N	Р	N			Р		Installation record	Υ		Visual insp during install or repair	Installed after lead ban	N
1964 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1975 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban			N	Р	N	1"		Р	SF	Installation record	Υ		Visual insp during install or repair	Installed after lead ban	N
1975 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban Installed after lead ban	1963 MINTEN WAY		N	Р	N	1"	2003	Р	SF	Installation record	Υ	2003	Visual insp during install or repair	Installed after lead ban	N
1975 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban 1976 MINTEN WAY  N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban Installed after lead ban	1964 MINTEN WAY		N	Р	N	1"	2003	Р	SF	Installation record	Υ	2003	Visual insp during install or repair	Installed after lead ban	N
1976 MINTEN WAY N P N 1" 2003 P SF Installation record Y 2003 Visual insp during install or repair Installed after lead ban	1975 MINTEN WAY		N	Р	N	1"		Р	SF	Installation record	Υ		Visual insp during install or repair	Installed after lead ban	N
			N	Р	N	1"		Р	SF		Υ				N
I LOUS I MALAINE III SUULI II	1982 MINTEN WAY			Р	N	1"	2003	Р	SF	Installation record	Υ	2003	Visual insp during install or repair	Installed after lead ban	N
			-					-	-						

1983 MINTEN WAY		N	Р	N	1"	2003	Р	SF	Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	N
1823 MISTY MOON WAY		N	Р	N	1"	2003	Р	SF	Installation record	Υ	2003	Visual insp during install or repair	Installed after lead ban	N
1824 MISTY MOON WAY		N	P	N	1"	2003	P	SF	Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	N
1830 MISTY MOON WAY		N	Р	N	1"	2003	Р	SF	Installation record	Υ	2003	Visual insp during install or repair	Installed after lead ban	N
1831 MISTY MOON WAY		N	Р	N	1"	2003	Р	SF	Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	N
1839 MISTY MOON WAY		N	Р	N	1"	2003	Р	SF	Installation record	Υ	2003	Visual insp during install or repair	Installed after lead ban	N
1843 MISTY MOON WAY		N	Р	N	1"	2003	P	SF	Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	N
1846 MISTY MOON WAY		N	Р	N	1"	2003	Р	SF	Installation record	Υ	2003	Visual insp during install or repair	Installed after lead ban	N
1851 MISTY MOON WAY		N	P	N	1"	2003	Р	SF	Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	N
1854 MISTY MOON WAY		N	P	N	1"	2003	P	SF	Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	N
1857 MISTY MOON WAY		N	P	N	1"	2003	P	SF	Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	N
1860 MISTY MOON WAY		N	P	N	1"	2003	P	SF	Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	N
1863 MISTY MOON WAY		N	P	N	1"	2003	P	SF	Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	N
1869 MISTY MOON WAY		N	P	N	1"	2003	P	SF	Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	N
2001 MORNING DEW LN		N	P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
2009 MORNING DEW LN		N N	P P	N N	1" 1"	2004	P P	SF SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
2017 MORNING DEW LN		N N	P			2004	P P		Installation record		2004	Visual insp during install or repair	Installed after lead ban	N
2022 MORNING DEW LN 2025 MORNING DEW LN		N N	P	N	1"	2004	Р D	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N N
		N N	P	N N	1" 1"	2004	Р Р	SF SF	Installation record	Y	2004 2004	Visual insp during install or repair	Installed after lead ban	• • • • • • • • • • • • • • • • • • • •
1517 MORNING MIST WAY 1525 MORNING MIST WAY		N	P	N N	1"	2004	<u>Р</u>	SF SF	Installation record Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban Installed after lead ban	N N
1533 MORNING MIST WAY		N	P	N	1"	2004	P	SF		Y	2004	Visual insp during install or repair		N
1541 MORNING MIST WAY		N N	P	N N	1"	2004	<u>Р</u>	SF SF	Installation record	V	2004	Visual insp during install or repair	Installed after lead ban Installed after lead ban	N N
1541 MORNING MIST WAY		N N	P	N N	1"	2004	Р Р	SF SF	Installation record Installation record	Y	2004	Visual insp during install or repair  Visual insp during install or repair	Installed after lead ban	N N
1557 MORNING MIST WAY		N	P	N	1"	2004	P P	SF SF	Installation record	Y	2004	Visual insp during install or repair  Visual insp during install or repair	Installed after lead ban	N N
1560 MORNING MIST WAY		N	P	N N	1"	2004	P P	SF SF	Installation record	Y	2004	Visual insp during install or repair  Visual insp during install or repair	Installed after lead ban	N
1565 MORNING MIST WAY		N	P	N	1"	2004	D	SF SF	Installation record	V	2004	Visual insp during install or repair  Visual insp during install or repair	Installed after lead ban	N N
1570 MORNING MIST WAY		N	P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1573 MORNING MIST WAY		N	P	N	1"	2004	D	SF	Installation record	· Y	2004	Visual insp during install or repair	Installed after lead ban	N
1581 MORNING MIST WAY		N	P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1589 MORNING MIST WAY		N	 P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1596 MORNING MIST WAY		N	 P	N	1"	2004	P	SF	Installation record	Υ Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1597 MORNING MIST WAY		N	P	N	1"	2004	Р	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1323 MOURNING DOVE CT		N	P	N	1"	1993	Р	SF	Installation record	Y	1993	Visual insp during install or repair	Installed after lead ban	N
1326 MOURNING DOVE CT		N	P	N	1"	1993	P	SF	Installation record	Y	1993	Visual insp during install or repair	Installed after lead ban	N
1348 MOURNING DOVE CT		N	P	N	1"	1993	P	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1353 MOURNING DOVE CT		N	P	N	1"	1993	P	SF	Installation record	Y	1993	Visual insp during install or repair	Installed after lead ban	N
1358 MOURNING DOVE CT		N	P	N	1"	1993	P	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1362 MOURNING DOVE CT		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1368 MOURNING DOVE CT		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1369 MOURNING DOVE CT		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1376 MOURNING DOVE CT		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1396 MOURNING DOVE CT		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1291 MOURNING DOVE LN		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1305 MOURNING DOVE LN		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1306 MOURNING DOVE LN		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1315 MOURNING DOVE LN		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
1316 MOURNING DOVE LN		N	Р	N	1"	1993	Р	SF	Installation record	Υ	1993	Visual insp during install or repair	Installed after lead ban	N
731 MYSTERY CT		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
734 MYSTERY CT		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
737 MYSTERY CT		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
742 MYSTERY CT		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
745 MYSTERY CT		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
750 MYSTERY CT		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
753 MYSTERY CT		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
803 MYSTIC CT		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
811 MYSTIC CT		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
814 MYSTIC CT		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
822 MYSTIC CT		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
825 MYSTIC CT		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
830 MYSTIC CT		N	Р	N	1"	2004	Р	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
833 MYSTIC CT		N	Р	N	1"	2004	Р	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
838 MYSTIC CT		N	Р	N	1"	2004	Р	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
841 MYSTIC CT		N	Р	N	1"	2004	Р	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
844 MYSTIC CT		N	Р	N	1"	2004	Р	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
845 MYSTIC CT		N	Р	N	1"	2004	Р	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
848 MYSTIC CT		N	P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1860 MID VALLEY DR	DELEERS CONSTRUCTION INC	N	P	N	8"	2001	P	NONRES	Installation record	Y	2001	Visual insp during install or repair	Installed after lead ban	N
1856 NIMITZ DR	SPORTS EMPORIUM	N	P	N	6"	2003	P	NONRES	Installation record	Y	2003	Visual insp during install or repair	Installed after lead ban	N
1861 NIMITZ DR	BAY LAKE REGIONAL PLANNING COMMISSION	N	P	N	1"	1996	P	NONRES	Installation record	Y	1996	Visual insp during install or repair	Installed after lead ban	N
		N.I.	P	N	1"	2003	Р	SF	Installation record	Υ	2003	Visual insp during install or repair	Installed after lead ban	N
1553 PARK HAVEN RD 1556 PARK HAVEN RD		N N	P	N	1"	2003	Р	SF	Installation record	Υ	2003	Visual insp during install or repair	Installed after lead ban	N

1651 PARK HAVEN RD	install or repair Installed after lead be install or repair Installed af	an N
1569 PARK HAVEN RD	install or repair Installed after lead be installed after lead be install or repair Installed after lead be instal	an N
1576 PARK HAVEN RD	install or repair Installed after lead be installed after lead be install or repair Installed after lead be instal	an N
1577 PARK HAVEN RD	install or repair Installed after lead be installed af	an N
1588 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1592 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1592 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1592 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1590 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1690 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1690 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1690 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1690 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1690 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1690 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1692 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1692 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1692 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1692 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1420 PAT IILLMAN ST NPN14 PNN12 2003 PSF Installation record Y 2003 Visual insp during 1420 PAT IILLMAN ST NPNN14 PNN14 2005 PSF Installation record Y 2005 Visual insp during 1420 PAT IILLMAN ST NPNN14 PNN14 2005 PSF Installation record Y 2005 Visual insp during 1439 PAT IILLMAN ST NPNN14 PNN14 2005 PSF Installation record Y 2005 Visual insp during 1439 PAT IILLMAN ST NPNN14 PNN14 2005 PSF Installation record Y 2005 Visual insp during 1439 PAT IILLMAN ST NPNN14 PNN14 2005 PSF Installation record Y 2005 Visual insp during 1439 PAT IILLMAN ST NPNN14 PNN14 2005 PSF Installation record Y 2005 Visual insp during 1439 PAT IILLMAN ST NPNN14 PNN14 2005 PSF Installation record Y 2005 Visual insp during 1439 PAT IILLMAN ST NPNN14 PNN14 2005 PSF Installation record Y 2005 Visual insp during 1449 PAT IILLMAN ST NPNN14 PNN14 2005 PSF Installation	install or repair Installed after lead be	an N
1588 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1592 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1592 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1592 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1590 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1690 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1690 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1690 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1690 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1690 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1690 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1692 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1692 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1692 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1692 PARK HAVEN RD NPN12 2003 PSF Installation record Y 2003 Visual insp during 1420 PAT IILLMAN ST NPN14 PNN12 2003 PSF Installation record Y 2003 Visual insp during 1420 PAT IILLMAN ST NPNN14 PNN14 2005 PSF Installation record Y 2005 Visual insp during 1420 PAT IILLMAN ST NPNN14 PNN14 2005 PSF Installation record Y 2005 Visual insp during 1439 PAT IILLMAN ST NPNN14 PNN14 2005 PSF Installation record Y 2005 Visual insp during 1439 PAT IILLMAN ST NPNN14 PNN14 2005 PSF Installation record Y 2005 Visual insp during 1439 PAT IILLMAN ST NPNN14 PNN14 2005 PSF Installation record Y 2005 Visual insp during 1439 PAT IILLMAN ST NPNN14 PNN14 2005 PSF Installation record Y 2005 Visual insp during 1439 PAT IILLMAN ST NPNN14 PNN14 2005 PSF Installation record Y 2005 Visual insp during 1439 PAT IILLMAN ST NPNN14 PNN14 2005 PSF Installation record Y 2005 Visual insp during 1449 PAT IILLMAN ST NPNN14 PNN14 2005 PSF Installation	install or repair Installed after lead be	an N
1885 PARK HAVEN RD	install or repair Installed after lead be	an N
1552 PARK HAVEN RD	install or repair Installed after lead be installed after le	an N
1600 PARK HAVEN RD	install or repair Installed after lead be installed after le	an N
1608 PARK HAVEN RD	install or repair Installed after lead be installed after le	an N
1609 PARK HAVEN RD	install or repair Installed after lead be instal	an N
1616 PARK HAVEN RD	install or repair Installed after lead be	an N
1617 PARK HAVEN RD	install or repair Installed after lead be installed after le	an N
1624 PARK HAVEN RD         N         P         N         1"         2003         P         SF         Installation record         Y         2003         Visual insp during           1625 PARK HAVEN RD         N         P         N         1"         2003         P         SF         Installation record         Y         2003         Visual insp during           1420 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1425 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1431 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1431 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1432 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         In	install or repair Installed after lead by installed af	an N
1624 PARK HAVEN RD         N         P         N         1"         2003         P         SF         Installation record         Y         2003         Visual insp during           1625 PARK HAVEN RD         N         P         N         1"         2003         P         SF         Installation record         Y         2003         Visual insp during           1420 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1425 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1431 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1431 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1432 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         In	install or repair Installed after lead by installed af	an N
1625 PARK HAVEN RD         N         P         N         1"         2003         P         SF         Installation record         Y         2003         Visual insp during           1420 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1426 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1431 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1431 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1432 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1432 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         I	install or repair Installed after lead be	an N
1420 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1425 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1426 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1431 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1432 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1438 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1442 PAT TILLMAN ST         N         P         N         1"         2005         P         SF	install or repair Installed after lead by	an N
1425 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1426 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1431 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1437 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1438 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1442 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1442 PAT TILLMAN ST         N         P         N         1"         2005         P         SF	install or repair install or repair install or repair install or repair installed after lead be installed or repair install or repair installed after lead be installed after lead be install or repair install or repair install or repair installed after lead be	an N
1426 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1431 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1432 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1437 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1438 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1442 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1442 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1443 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1443 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1449 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1449 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1450 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1450 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1456 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1456 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during	install or repair Installed after lead be	an N an N an N an N an N
1431 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1432 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1437 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1438 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1438 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1442 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1443 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1449 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1449 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1450 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1450 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1456 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1456 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1456 PAT TILLMAN ST	install or repair	an N an N an N
1432 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1437 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1438 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1442 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1442 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1443 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1449 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1450 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1455 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1456 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1456 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1456 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during	install or repair Installed after lead be	an N an N an N
1437 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1438 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1442 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1449 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1449 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1450 PAT TILLMAN ST         N         P         N         1"         2005         P         SF         Installation record         Y         2005         Visual insp during           1456 PAT TILLMAN ST         N         P         N         1"         2005         P         SF	install or repair Installed after lead based installed af	an N an N
1438 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1442 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1443 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1449 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1449 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1450 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1455 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1456 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1456 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1456 PAT TILLMAN ST	install or repair Installed after lead based install or repair Installed after lead based install or repair Installed after lead based installed after lead based installed after lead based installed after lead based in the second in th	an N
1442 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1443 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1449 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1449 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1450 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1455 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1456 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1456 PAT TILLMAN ST	install or repair Installed after lead ba install or repair Installed after lead ba	
1442 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1443 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1449 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1449 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1450 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1455 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1456 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1456 PAT TILLMAN ST	install or repair Installed after lead ba install or repair Installed after lead ba	
1443 PAT TILLMAN STNPN1"2005PSFInstallation recordY2005Visual insp during1449 PAT TILLMAN STNPN1"2005PSFInstallation recordY2005Visual insp during1450 PAT TILLMAN STNPN1"2005PSFInstallation recordY2005Visual insp during1455 PAT TILLMAN STNPN1"2005PSFInstallation recordY2005Visual insp during1456 PAT TILLMAN STNPN1"2005PSFInstallation recordY2005Visual insp during	install or repair Installed after lead ba	un IV
1449 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1450 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1450 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1456 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1456 PAT TILLMAN ST  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1456 PAT TILLMAN ST		
1450 PAT TILLMAN STNPN1"2005PSFInstallation recordY2005Visual insp during1455 PAT TILLMAN STNPN1"2005PSFInstallation recordY2005Visual insp during1456 PAT TILLMAN STNPN1"2005PSFInstallation recordY2005Visual insp during		
1455 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during 1456 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during	•	
1456 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during	·	
	install or repair Installed after lead ba	an N
1461 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual inso during	install or repair Installed after lead ba	an N
	install or repair Installed after lead ba	an N
1464 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during	install or repair Installed after lead ba	an N
1467 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during	•	
1470 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during	·	
1 0	·	
1472 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during	·	
1474 PAT TILLMAN ST N P N 1" 2005 P SF Installation record Y 2005 Visual insp during	install or repair Installed after lead ba	an N
1208 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	install or repair Installed after lead ba	an N
1210 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	install or repair Installed after lead ba	an N
1212 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	•	
1214 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	·	
	·	
12 TO TOND VIEW OIL V	·	
1217 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during		
1218 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	install or repair Installed after lead ba	an N
1219 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	install or repair Installed after lead ba	an N
1221 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	install or repair Installed after lead ba	an N
1222 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	· · · · · · · · · · · · · · · · · · ·	an N
1224 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	•	
	·	
·	•	•
1228 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	•	-
1236 POND VIEW CIRCLE N P SF Installation record Y 2004 Visual insp during		
1238 POND VIEW CI N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	install or repair Installed after lead ba	an N
1240 POND VIEW CI N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	install or repair Installed after lead ba	an N
1241 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	install or repair Installed after lead ba	an N
1242 POND VIEW CI N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	install or repair Installed after lead ba	an N
1243 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	•	-
1244 POND VIEW CIRCLE N P SF Installation record Y 2004 Visual insp during	· · · · · · · · · · · · · · · · · · ·	
	·	-
1245 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during		
1246 POND VIEW CIRCLE N P SF Installation record Y 2004 Visual insp during	· · · · · · · · · · · · · · · · · · ·	
1247 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	•	an N
1249 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	install or repair Installed after lead ba	an N
1251 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	install or repair Installed after lead ba	an N
1253 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	· · · · · · · · · · · · · · · · · · ·	
1255 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	·	
	· · · · · · · · · · · · · · · · · · ·	
	•	
1263 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	•	
1265 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	·	
1267 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	install or repair Installed after lead ba	an N
1273 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	install or repair Installed after lead ba	an N
1275 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	install or repair Installed after lead ba	an N
1277 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	·	
1279 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	•	
	· · · · · · · · · · · · · · · · · · ·	
1281 POND VIEW CIR N P N 1" 2004 P SF Installation record Y 2004 Visual insp during	install or repair Installed after lead ba	aii IV

1283 POND VIEW CIR 1289 POND VIEW CIR 1291 POND VIEW CIR 1293 POND VIEW CIR 1294 POND VIEW CIRCLE 1295 POND VIEW CIRCLE 1296 POND VIEW CIRCLE 1298 POND VIEW CIRCLE 1315 POND VIEW CIRCLE 1317 POND VIEW CIR 1317 POND VIEW CIR 1319 POND VIEW CIR 1321 POND VIEW CIR 1321 POND VIEW CIR 1323 POND VIEW CIR 1333 POND VIEW CIR 1335 POND VIEW CIR	N N N N N N N N N N N N N N N N N N N	P P P P P P P P P P P P P P P P	N N N N N N N N	1" 1" 1" 1" 1" 1" 1" 1" 1" 1" 1"	2004 2004 2004 2004 2004 2004 2004 2004	P P P P P	SF SF SF SF SF	Installation record Installation record Installation record Installation record Installation record	Y Y Y Y Y	2004 2004 2004 2004 2004	Visual insp during install or repair	Installed after lead ban Installed after lead ban Installed after lead ban Installed after lead ban	N N N N
1291 POND VIEW CIR 1293 POND VIEW CIR 1294 POND VIEW CIRCLE 1295 POND VIEW CIRCLE 1296 POND VIEW CIRCLE 1298 POND VIEW CIRCLE 1315 POND VIEW CIR 1317 POND VIEW CIR 1319 POND VIEW CIR 1321 POND VIEW CIR 1329 POND VIEW CIR 1331 POND VIEW CIR 1331 POND VIEW CIR 1333 POND VIEW CIR	N N N N N N N N N N N	P P P P P P P P P P P	N N N N N N	1" 1" 1" 1" 1" 1" 1" 1"	2004 2004 2004 2004 2004	P P P	SF SF SF	Installation record Installation record	Y	2004 2004	Visual insp during install or repair Visual insp during install or repair	Installed after lead ban Installed after lead ban	N N
1293 POND VIEW CIR 1294 POND VIEW CIRCLE 1295 POND VIEW CIRCLE 1296 POND VIEW CIRCLE 1298 POND VIEW CIRCLE 1315 POND VIEW CIR 1317 POND VIEW CIR 1319 POND VIEW CIR 1321 POND VIEW CIR 1329 POND VIEW CIR 1331 POND VIEW CIR 1331 POND VIEW CIR 1333 POND VIEW CIR	N N N N N N N N N	P P P P P P P P P	N N N N N	1" 1" 1" 1" 1"	2004 2004 2004 2004	P P P	SF SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1294 POND VIEW CIRCLE 1295 POND VIEW CIR 1296 POND VIEW CIRCLE 1298 POND VIEW CIRCLE 1315 POND VIEW CIR 1317 POND VIEW CIR 1319 POND VIEW CIR 1321 POND VIEW CIR 1329 POND VIEW CIR 1331 POND VIEW CIR 1331 POND VIEW CIR 1333 POND VIEW CIR	N N N N N N N N N	P P P P P P P	N N N N N	1" 1" 1" 1" 1"	2004 2004 2004	P P	SF		<u> </u>				
1295 POND VIEW CIR 1296 POND VIEW CIRCLE 1298 POND VIEW CIRCLE 1315 POND VIEW CIR 1317 POND VIEW CIR 1319 POND VIEW CIR 1321 POND VIEW CIR 1321 POND VIEW CIR 1329 POND VIEW CIR 1331 POND VIEW CIR 1331 POND VIEW CIR 1333 POND VIEW CIR	N N N N N N N N	P P P P P	N N N N	1" 1" 1" 1"	2004 2004	P		Installation record	Y	2004	and the second s		N
1296 POND VIEW CIRCLE 1298 POND VIEW CIRCLE 1315 POND VIEW CIR 1317 POND VIEW CIR 1319 POND VIEW CIR 1321 POND VIEW CIR 1329 POND VIEW CIR 1331 POND VIEW CIR 1331 POND VIEW CIR 1333 POND VIEW CIR	N N N N N N N N	P P P P P	N N N	1" 1" 1"	2004		SF				Visual insp during install or repair	Installed after lead ban	IN
1298 POND VIEW CIRCLE 1315 POND VIEW CIR 1317 POND VIEW CIR 1319 POND VIEW CIR 1321 POND VIEW CIR 1329 POND VIEW CIR 1331 POND VIEW CIR 1333 POND VIEW CIR	N N N N N N N	P P P P	N N N	1" 1"		Р		Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1315 POND VIEW CIR 1317 POND VIEW CIR 1319 POND VIEW CIR 1321 POND VIEW CIR 1329 POND VIEW CIR 1331 POND VIEW CIR 1333 POND VIEW CIR	N N N N N N	P P P	N N	1"	2004	•	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1317 POND VIEW CIR 1319 POND VIEW CIR 1321 POND VIEW CIR 1329 POND VIEW CIR 1331 POND VIEW CIR 1333 POND VIEW CIR	N N N N N	P P P	N		_00,	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1319 POND VIEW CIR 1321 POND VIEW CIR 1329 POND VIEW CIR 1331 POND VIEW CIR 1333 POND VIEW CIR	N N N N	P P	**		2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1321 POND VIEW CIR 1329 POND VIEW CIR 1331 POND VIEW CIR 1333 POND VIEW CIR	N N N N	P	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1321 POND VIEW CIR 1329 POND VIEW CIR 1331 POND VIEW CIR 1333 POND VIEW CIR	N N N	<u> </u>		1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1329 POND VIEW CIR 1331 POND VIEW CIR 1333 POND VIEW CIR	N N N	P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1331 POND VIEW CIR 1333 POND VIEW CIR	N N	<u> </u>	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1333 POND VIEW CIR	N	Р	N	1"	2004	<u>.</u> Р	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
		P P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
	NI NI	P	N N	1"	2004	<u>Р</u>	SF		Y	2004			N
	N N	P	N N	1"	2004	<u>Р</u>	SF SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1337 POND VIEW CIR		·						Installation record	•		Visual insp during install or repair	Installed after lead ban	
1339 POND VIEW CIR	N	P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1349 POND VIEW CIR	N	P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1351 POND VIEW CIR	N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1353 POND VIEW CIR	N	P	N	1"	2004	P	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1355 POND VIEW CIR	N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
2100 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2101 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2102 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2103 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2105 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2104 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2107 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2111 POTTER DR	N	P	N	1"	2006	P	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2109 POTTER DR	N	Р	N	1"	2006	P	SF	Installation record	· Y	2006	Visual insp during install or repair	Installed after lead ban	N
2110 POTTER DR	N N	P	N	1"	2006	P	SF	Installation record		2006	Visual insp during install or repair	Installed after lead ban	N
2114 POTTER DR	N	P	N	1"	2006	D	SF	Installation record	V	2006	Visual insp during install or repair	Installed after lead ban	N
2115 POTTER DR	N N	P	N N	1"	2006	<u>Р</u>	SF		Y	2006			N
	**	•						Installation record	•		Visual insp during install or repair	Installed after lead ban	
2117 POTTER DR	N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2116 POTTER DR	N	P	N	1"	2006	P	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2118 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2120 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2119 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2122 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2121 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2123 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2124 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2125 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2126 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2127 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2128 POTTER DR	N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2129 POTTER DR	N N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2130 POTTER DR	N	P P	N	1"	2006	<u>Р</u>	SF	Installation record	V	2006	Visual insp during install or repair	Installed after lead ban	N
2131 POTTER DR	N N	P	N N	1"	2006	<u>Р</u>	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
	N	P	N N	1"	2006	P P	SF		Y	2006			N
2132 POTTER DR		·						Installation record	•		Visual insp during install or repair	Installed after lead ban	
2133 POTTER DR	N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2134 POTTER DR	N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2135 POTTER DR	N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
2137 POTTER DR	N	P	N	1"	2006	P	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2136 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2138 POTTER DR	N	Р	N	1"	2006	P	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2152 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2153 POTTER DR	N	Р	N	1"	2006	P	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2154 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2142 POTTER DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
2143 POTTER DR	N	Р	N	1"	2014	Р	SF	Installation record	Υ	2014	Visual insp during install or repair	Installed after lead ban	N
2144 POTTER DR	N	Р	N	1"	2014	P	SF	Installation record	Υ	2014	Visual insp during install or repair	Installed after lead ban	N
2145 POTTER DR	N	P	N	1"	2014	<u>.</u> Р	SF	Installation record	Y	2014	Visual insp during install or repair	Installed after lead ban	N
2146 POTTER DR	N	P	N	1"	2014	P	SF	Installation record	Y	2014	Visual insp during install or repair	Installed after lead ban	N
2147 POTTER DR	N	P P	N	1"	2014	P P	SF	Installation record	Y	2014	Visual insp during install or repair	Installed after lead ban	N
2148 POTTER DR	N	Р Р	N N	1"	2014	<u>Р</u>	SF		Y	2014		Installed after lead ban	N
2263 GRINGOTTS WY	N N	Р Р	N N	1"		Р Р		Installation record	Y		Visual insp during install or repair		
		•			2015	P P	SF	Installation record	T	2015	Visual insp during install or repair	Installed after lead ban	N
2150 POTTER DR	N	P	N N	1"	2014		SF	Installation record	Y	2014	Visual insp during install or repair	Installed after lead ban	N
1426 QUARRY PARK DR	N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1432 QUARRY PARK DR	N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1438 QUARRY PARK DR	N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N

1445 QUARRY PARK DR		N	Р	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1456 QUARRY PARK DR		N	Р	N	1"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1461 QUARRY PARK DR		N	Р	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1467 QUARRY PARK DR		N	P	N	1"	2005	P	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
1485 QUARRY PARK DR		N	Р	N	1"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1503 QUARRY PARK DR		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1511 QUARRY PARK DR		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1550 QUARRY PARK DR	TOONEN COMPANIES INC	N	P	N	8"	2005	P	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
1519 QUARRY PARK DR		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1527 QUARRY PARK DR		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1535 QUARRY PARK DR		N	Р -	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1554 QUARRY PARK DR	TOONEN COMPANIES INC	N	P	N	8"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1558 QUARRY PARK DR	TOONEN COMPANIES INC	N	P	N	8"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1562 QUARRY PARK DR	TOONEN COMPANIES INC	N	Р .	N	8"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1566 QUARRY PARK DR	TOONEN COMPANIES INC	N N	P	N N	8"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1570 QUARRY PARK DR	TOONEN COMPANIES INC	**	Р	N	8" 1"	2005	P P	SF SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1473 QUARRY PARK DR	TOONEN COMPANIES INC	N N	P P	N N		2005	<u> </u>		Installation record	<u>.</u>	2005	Visual insp during install or repair	Installed after lead ban	N
1574 QUARRY PARK DR	TOONEN COMPANIES INC	• • • • • • • • • • • • • • • • • • • •	P P	N	8"	2005 2005	Р Р	SF SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1578 QUARRY PARK DR	TOONEN COMPANIES INC	N N	P D	N N	8" 1"		P P		Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1479 QUARRY PARK DR	TOONEN COMPANIES INC	N N	P P	N N	8"	2005 2005	Р Р	SF SF	Installation record	Y	2005 2005	Visual insp during install or repair	Installed after lead ban	N
1582 QUARRY PARK DR 1586 QUARRY PARK DR	TOONEN COMPANIES INC	N N	P P	N N	8" 8"	2005	P	SF SF	Installation record Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N N
		N N	P D	N N	8"	2005	P P	SF SF		Y	2005	Visual insp during install or repair	Installed after lead ban	
1590 QUARRY PARK DR 1594 QUARRY PARK DR	TOONEN COMPANIES INC TOONEN COMPANIES INC	N N		N N	8"	2005	Р Р	SF SF	Installation record Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban Installed after lead ban	N N
1598 QUARRY PARK DR	TOONEN COMPANIES INC	N N	P D	N N	8"	2005	P P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1625 QUARRY PARK DR	TOWN OF LAWRENCE	N N	P D	N N	2"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair  Visual insp during install or repair	Installed after lead ban	N
1655 QUARRY PARK DR	PRECISION CUT STONE	N N	D P	N N	2"	2005	P P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1742 QUARRY PARK DR	FRECISION COT STONE	N	г D	N N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
3046 QUARRY PARK DR	TOONEN COMPANIES INC	N N	D	N N	8"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
3046 QUARRY PARK B	TOONEN COMPANIES INC	N N	D D	N N	8"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
801 QUIDDITCH CT	TOONEN COMPANIES INC	N N	D D	N N	1"	2014	P P	SF	Installation record	Y	2014	Visual insp during install or repair	Installed after lead ban	N
802 QUIDDITCH CT		N N	D D	N	1"	2014	P	SF	Installation record	Y	2014	Visual insp during install or repair	Installed after lead ban	N
804 QUIDDITCH CT		N N	P	N	1"	2014	P	SF	Installation record	Y	2014	Visual insp during install or repair	Installed after lead ban	N
806 QUIDDITCH CT		N N	P	N	1"	2014	Р	SF	Installation record	Υ Υ	2014	Visual insp during install or repair	Installed after lead ban	N
808 QUIDDITCH CT		N N	D	N	1"	2014	P	SF	Installation record	Y	2014	Visual insp during install or repair	Installed after lead ban	N
809 QUIDDITCH CT		N N	P	N	1"	2014	Р	SF	Installation record	Y	2014	Visual insp during install or repair	Installed after lead ban	N
807 QUIDDITCH CT		N N	Р	N	1"	2014	P	SF	Installation record	Y	2014	Visual insp during install or repair	Installed after lead ban	N
805 QUIDDITCH CT		N N	Р	N	1"	2014	Р	SF	Installation record	Υ Υ	2014	Visual insp during install or repair	Installed after lead ban	N
841 RIVERS RUN		N N	Р	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
839 RIVERS RUN		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
818 RIVERS RUN		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
806 RIVERS RUN		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
830 RIVERS RUN		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
836 RIVERS RUN		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
842 RIVERS RUN		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
854 RIVERS RUN		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
812 RIVERS RUN		N	P	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
800 RIVERS RUN		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
843 RIVERS RUN		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
1326 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1329 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1334 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1335 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1345 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1354 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1357 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1364 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1377 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1386 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1420 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1404 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1423 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1426 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1436 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1456 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1470 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1473 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1476 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1484 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1491 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1496 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1510 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N

1521 SAND ACRES DR	Tom Perock	N	Р	N	1"	1995	С	SF	Installation record	Y	1995	Visual insp during install or repair	Installed after lead ban	N
1601 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1611 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1614 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1627 SAND ACRES DR		N	Р	N	1"	1995	P	SF	Installation record	Y	1995	Visual insp during install or repair	Installed after lead ban	N
1639 SAND ACRES DR		N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1641 SAND ACRES DR		N	P	N	1"	1995	P	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1644 SAND ACRES DR		N	P	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1648 SAND ACRES DR		N	P	N	1"	1995	P	SF	Installation record	Y	1995	Visual insp during install or repair	Installed after lead ban	N
1649 SAND ACRES DR, UNIT A	ROBINSON HEATING & COOLING	N	P	N	2"	1995	P	NONRES	Installation record	Y	1995	Visual insp during install or repair	Installed after lead ban	N
1649 SAND ACRES RD UNIT B	FIRST CHOICE METAL FINISHING	N	Р -	N	2"	1995	P	NONRES	Installation record	Y	1995	Visual insp during install or repair	Installed after lead ban	N
1652 SAND ACRES DR		N	P	N	1"	1995	Р	SF	Installation record	Y	1995	Visual insp during install or repair	Installed after lead ban	N
1672 SAND ACRES DR		N	Р	N	1"	1995	P	SF	Installation record	Y	1995	Visual insp during install or repair	Installed after lead ban	N
1676 SAND ACRES DR	DEGLET COLLOCU OF CANUNE TRAINING	N	Р	N	1"	1995	P	SF	Installation record	Y	1995	Visual insp during install or repair	Installed after lead ban	N
1677 SAND ACRES DR UNIT B	BECKET SCHOOL OF CANINE TRAINING	N N	P	N N	1"	2018	P	NONRES	Installation record	Y	2018	Visual insp during install or repair	Installed after lead ban	N
1680 SAND ACRES DR	ININION/ATINE DEODEDTIES		Р Р	N	1" 6"	1995 2004	P P	SF	Installation record	Y	1995 2004	Visual insp during install or repair	Installed after lead ban	N
1700 SAND ACRES DR #2	INNOVATIVE PROPERTIES	N N	Р Р	N N			<u> </u>	NONRES	Installation record	Y		Visual insp during install or repair	Installed after lead ban	N
1700 SAND ACRES DR #3	MIDWEST RETIREMENT LLC	* * *	Р Р	N	6" 6"	2004 2004	P P	NONRES	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1700 SAND ACRES DR #4 1700 SAND ACRES DR #5	FOXX FITNESS LLC	N N	Р Р	N N	6"	2004		NONRES	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1700 SAND ACRES DR #5	MAIN STREET MANAGEMENT SGAMBATI PIZZA	N N	P P	N N	6"	2004	P P	NONRES NONRES	Installation record Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1700 SAND ACRES DR-POND	INNOVATIVE PROPERTIES LLC	N N	P D	N N	6"	2004	P	NONRES	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N N
3805 SAND ACRES DR-POND	INNOVATIVE PROPERTIES LLC	N N	P D	N	1"	1999	P	SF		Y	1999	Visual insp during install or repair	Installed after lead ban Installed after lead ban	N N
3808 SAND ACRES DR		N N	P D	N N	1"	1999	P	SF	Installation record Installation record	Y	1999	Visual insp during install or repair  Visual insp during install or repair	Installed after lead ban	N N
3825 SAND ACRES DR		N N	P D	N N	1"	1999	P P	SF SF	Installation record	Y	1999	<u> </u>	Installed after lead ban	N N
3839 SAND ACRES DR		N N	P D	N	1"	1999	P	SF	Installation record	Y	1999	Visual insp during install or repair  Visual insp during install or repair	Installed after lead ban	N
1446 SANDY SPRINGS CT		N N	D D	N	1"	2004	P P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1449 SANDY SPRINGS CT		N	<u>г</u>	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1466 SANDY SPRINGS CT		N	D D	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1467 SANDY SPRINGS CT		N N	<u>г</u>	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1475 SANDY SPRINGS CT		N N	D D	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1478 SANDY SPRINGS CT		N	D D	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1771 SANDY SPRINGS RD		N	D D	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1774 SANDY SPRINGS RD		N	P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1782 SANDY SPRINGS RD		N	D	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1787 SANDY SPRINGS RD		N	P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1795 SANDY SPRINGS RD		N	P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1798 SANDY SPRINGS RD		N	P	N	1"	2004	Р	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1804 SANDY SPRINGS RD		N	P	N	1"	2004	Р	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1808 SANDY SPRINGS RD		N	P	N	1"	2004	P	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1811 SANDY SPRINGS RD		N	P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1825 SANDY SPRINGS RD		N	P	N	1"	2004	P	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1830 SANDY SPRINGS RD		N	P	N	1"	2004	Р	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1831 SANDY SPRINGS RD		N	P	N	1"	2004	P	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1832 SANDY SPRINGS RD		N	P	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1836 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1837 SANDY SPRINGS RD		N	P	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1838 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1842 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1843 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1844 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1848 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1849 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1850 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1865 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1876 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1881 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1884 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1886 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1890 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1892 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1896 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1902 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1905 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1908 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1911 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1914 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1916 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1919 SANDY SPRINGS RD					1"		Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1919 SANDY SPRINGS RD 1920 SANDY SPRINGS RD		N	Р	N	T	2004	г	JI	installation record		_00.	tiodai mop daim 6 motan or repair	mistanca arter icaa ban	
		N N	P P	N N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N

1928 SANDY SPRINGS RD		N	P	N	1"	2004	Р	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1930 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1931 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1934 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1936 SANDY SPRINGS RD		N	P	N	1"	2004	P	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1940 SANDY SPRINGS RD		N	D	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1943 SANDY SPRINGS RD		N		N N	1"	2004	P	SF		Y	2004			N
			<u> </u>						Installation record	<u> </u>		Visual insp during install or repair	Installed after lead ban	
1946 SANDY SPRINGS RD		N	P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1952 SANDY SPRINGS RD		N	P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1958 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1961 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1970 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1973 SANDY SPRINGS RD		N	P	N	1"	2004	P	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1978 SANDY SPRINGS RD		N	D	N	1"	2004	Р	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1986 SANDY SPRINGS RD		N		N N	1"	2004	P	SF		Y	2004			
			P D						Installation record	<u> </u>		Visual insp during install or repair	Installed after lead ban	N
1990 SANDY SPRINGS RD		N	Р -	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
1994 SANDY SPRINGS RD		N	P	N	1"	2004	Р	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
2002 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
2017 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
2010 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
2018 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
2025 SANDY SPRINGS RD		N	P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
2026 SANDY SPRINGS RD		N	D	N N	1"	2004	P	SF		· Y	2004	Visual insp during install or repair		N
		* *	P P						Installation record	·		<u> </u>	Installed after lead ban	
2033 SANDY SPRINGS RD		N	P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
2034 SANDY SPRINGS RD		N	P	N	1"	2004	Р	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
2041 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
2042 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
2049 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
2050 SANDY SPRINGS RD		N	P	N	1"	2004	P	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
2057 SANDY SPRINGS RD		N	D	N	1"	2004	Р	SF	Installation record	Υ Υ	2004	Visual insp during install or repair	Installed after lead ban	N
		• • • • • • • • • • • • • • • • • • • •								-				
2058 SANDY SPRINGS RD		N	P	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
2065 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
2066 SANDY SPRINGS RD		N	Р	N	1"	2004	P	SF	Installation record	Y	2004	Visual insp during install or repair	Installed after lead ban	N
2073 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
2074 SANDY SPRINGS RD		N	Р	N	1"	2004	Р	SF	Installation record	Υ	2004	Visual insp during install or repair	Installed after lead ban	N
1702 SCHEURING RD - A	PDQ MANUFACTURING	N	Р	N	10"	1998	Р	NONRES	Installation record	Υ	1998	Visual insp during install or repair	Installed after lead ban	N
1698 SCHEURING RD - B	PDQ LASER BUILDING	N		N	10"	1998	P	NONRES	Installation record	Y	1998	Visual insp during install or repair	Installed after lead ban	N
1702 SCHEURING RD - C	PDQ (MFG-CARWASH)	N	D	N N	10"	1998	P	NONRES	Installation record	Y	1998	Visual insp during install or repair		N
	,		'									1 0 1	Installed after lead ban	
1711 SCHEURING RD	JONES SIGN CO.	N	P	N	8"	2007	P	NONRES	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	N
1711 SCHEURING RD #B	JONES SIGN	N	Р	N	8"	2007	Р	NONRES	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	N
1740 SCHEURING RD	FOX COMMUNITIES CREDIT UNION	N	Р	N	1"	1997	P	NONRES	Installation record	Y	1997	Visual insp during install or repair	Installed after lead ban	N
1800 SCHEURING RD	SCHEURING ROAD T.I.C. GROUP	N	Р	N	8"	2000	Р	NONRES	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
1800 SCHEURING RD #A	LAMAR ADVERTISING	N	Р	N	8"	2000	Р	NONRES	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
1855 SCHEURING RD	TOONEN COMPANIES INC	N	Р	N	8"	2000	Р	NONRES	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
1839 SCHEURING RD	ORTHODONTIC SPECIALISTS	N	D	N	8"	2000	Р	NONRES	Installation record	Υ Υ	2000	Visual insp during install or repair	Installed after lead ban	N
		N	D							Y		<u> </u>		
1839A SCHEURING RD	KAMINSKI DENTAL OFFICE	**	P -	N	2"	2000	P	NONRES	Installation record	-	2000	Visual insp during install or repair	Installed after lead ban	N
1851 SCHEURING RD	TOONEN COMPANIES INC	N	Р	N	8"	2000	Р	MF	Installation record	Y	2000	Visual insp during install or repair	Installed after lead ban	N
1853 SCHEURING RD	TOONEN COMPANIES INC	N	Р	N	8"	2000	Р	MF	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
1857 SCHEURING RD	TOONEN COMPANIES INC	N	Р	N	8"	2000	Р	MF	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
1861 SCHEURING RD	CREATIVE KIDS, M. WILLEMS	N	Р	N	8"	2000	Р	SCH/DC	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
1880 SCHEURING RD	A6 DE PERE LLC	N	Р	N	8"	2000	Р	NONRES	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
1951 SCHEURING RD	TOONEN COMPANIES OFFICE	N	P	N	8"	2000	Р	MF	Installation record	Y	2000	Visual insp during install or repair	Installed after lead ban	N
1953 SCHEURING RD	TOONEN COMPANIES INC	N	D	N N	8"	2000	P	MF	Installation record	Y	2000	Visual insp during install or repair	Installed after lead ban	N
		N N	D D				-			Y				
1955 SCHEURING RD	TOONEN COMPANIES INC	**	r	N	8"	2000	P	MF	Installation record		2000	Visual insp during install or repair	Installed after lead ban	N
1957 SCHEURING RD	TOONEN COMPANIES INC	N	Р	N	8"	2000	P	MF	Installation record	Y	2000	Visual insp during install or repair	Installed after lead ban	N
1959 SCHEURING RD	TOONEN COMPANIES INC	N	Р	N	8"	2000	Р	MF	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
1961 SCHEURING RD	TOONEN COMPANIES INC	N	Р	N	8"	2000	Р	MF	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
1963 SCHEURING RD	TOONEN COMPANIES INC	N	Р	N	8"	2000	Р	MF	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
1965 SCHEURING RD	TOONEN COMPANIES INC	N	Р	N	8"	2000	Р	MF	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
1967 SCHEURING RD	TOONEN COMPANIES INC	N	D D	N	8"	2000	Р	MF	Installation record	Υ Υ	2000	Visual insp during install or repair	Installed after lead ban	N
1969 SCHEURING RD	TOONEN COMPANIES INC	N	D	N N	8"	2000	P	MF	Installation record	Y	2000	Visual insp during install or repair	Installed after lead ban	N
		N N	P D							<u> </u>		<u> </u>		
1971 SCHEURING RD	TOONEN COMPANIES INC		Ρ -	N	8"	2000	P	MF	Installation record	Y	2000	Visual insp during install or repair	Installed after lead ban	N
1973 SCHEURING RD	TOONEN COMPANIES INC	N	Р	N	8"	2000	Р	MF	Installation record	Y	2000	Visual insp during install or repair	Installed after lead ban	N
1975 SCHEURING RD	TOONEN COMPANIES INC	N	Р	N	8"	2000	Р	MF	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
1977 SCHEURING RD	TOONEN COMPANIES INC	N	Р	N	8"	2000	Р	MF	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
- · · · · · · · · · · · · · · · · · · ·	TOONEN COMPANIES INC	N	Р	N	8"	2000	Р	MF	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
		N	P	N	8"	2000	Р	MF	Installation record	Υ Υ	2000	Visual insp during install or repair	Installed after lead ban	N
1979 SCHEURING RD	TOONEN COMPANIES INC	• •	•			2000	P	MF	Installation record	Y	2000	Visual insp during install or repair	Installed after lead ban	N
1979 SCHEURING RD 1981 SCHEURING RD	TOONEN COMPANIES INC	N	D	N				IVII	mstanation record		2000	visuai irisp uurilig iristall Ul Tepall	ilistalicu altel iedu ball	IN
1979 SCHEURING RD 1981 SCHEURING RD 1983 SCHEURING RD	TOONEN COMPANIES INC	N N	P	N	8"				Installation recent	V	2000	Visual inco during install an arrain		N.I.
1979 SCHEURING RD 1981 SCHEURING RD 1983 SCHEURING RD 1985 SCHEURING RD	TOONEN COMPANIES INC TOONEN COMPANIES INC	N	P P	N	8"	2000	Р	MF	Installation record	Y	2000	Visual insp during install or repair	Installed after lead ban	N
1979 SCHEURING RD 1981 SCHEURING RD 1983 SCHEURING RD 1985 SCHEURING RD 1987 SCHEURING RD	TOONEN COMPANIES INC TOONEN COMPANIES INC TOONEN COMPANIES INC	N N	P P P	N N	8" 8"	2000 2000	P P	MF MF	Installation record	Y	2000	Visual insp during install or repair	Installed after lead ban Installed after lead ban	N
1979 SCHEURING RD 1981 SCHEURING RD 1983 SCHEURING RD 1985 SCHEURING RD	TOONEN COMPANIES INC TOONEN COMPANIES INC	N	P P P	N	8"	2000	Р	MF		·		· • • · · · · · · · · · · · · · · · · ·	Installed after lead ban	

The Content of Conte															
March   Marc		TOONEN COMPANIES INC		P		8"	2000		MF	Installation record	Y	2000	<u> </u>		N
March   Marc				Р				<del>-</del>			· · · · · · · · · · · · · · · · · · ·				N
March   Marc		TOONEN COMPANIES INC		P	N			Р		Installation record			Visual insp during install or repair	Installed after lead ban	N
19.59   19.5		TOONEN COMPANIES INC	N	Р	N	8"		Р	MF	Installation record	Υ		Visual insp during install or repair	Installed after lead ban	N
160   160	3 SCHEURING RD	TOONEN COMPANIES INC	N	Р	N	8"	2000	Р	MF	Installation record	Y	2000	Visual insp during install or repair	Installed after lead ban	N
Second   S	1 SCHEURING RD	TOONEN COMPANIES INC	N	Р	N	8"	2000	Р	MF	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
200   100	5 SCHEURING RD	TOONEN COMPANIES INC	N	P	N	8"	2000	Р	MF	Installation record	Υ	2000	Visual insp during install or repair	Installed after lead ban	N
19   19   19   19   19   19   19   19	3 SCHEURING RD		N	Р	N	1"	2015	Р	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
The part of the	0 SHADOW RIDGE WAY	SHADOW RIDGE LLC	N	Р	N	8"	2002	Р	MF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1.   1.   1.   1.   1.   1.   1.   1.	8 SHADOW RIDGE WAY	SHADOW RIDGE LLC	N	Р	N	8"	2002	Р	MF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
2.5   Selection (CES)   CES		SHADOW RIDGE LLC	N	Р	N	8"		Р	MF		Υ		Visual insp during install or repair		N
200   100   200			N	Р	N	8"		Р	MF		Υ		· • ·		N
Part				Р				-			-				N
No.   1				D							<u>.</u>				N
19.5 MEMORY MOST WAY   1		SHADOW RIDGE EEC	**	<u>г</u>				•							N
1.00   1.00				P D											N N
Separation Mode Work   Mode			**	P P				<del>-</del>							
Figure   Property				Р				<u> </u>			<u>.</u>		· • ·		N
1500 BMADDY RICKER WAY				Р				-			-				N
1.00   1.00				P											N
19.58   19.50   19.5			**	Р				<del>-</del>							N
10.55 SHADOW RIDGE WAY				P						Installation record			Visual insp during install or repair	Installed after lead ban	N
1988   1986	8 SHADOW RIDGE WAY		N	Р	N		2001	Р	SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	N
1965 FEMOLOW RINGE WAY	3 SHADOW RIDGE WAY		N	Р	N	1"	2001	Р	SF	Installation record	Y	2001	Visual insp during install or repair	Installed after lead ban	N
1975 SHADOW RIDGE WAY	6 SHADOW RIDGE WAY		N	Р	N	1"	2001	Р	SF	Installation record	Υ	2001	Visual insp during install or repair	Installed after lead ban	N
1972 EMPADOW RIDGE WAY	4 SHADOW RIDGE WAY		N	Р	N	1"	2001	Р	SF	Installation record	Υ	2001	Visual insp during install or repair	Installed after lead ban	N
1809 SEMON RIDGE WAY	1 SHADOW RIDGE WAY		N	Р	N	1"	2001	Р	SF	Installation record	Υ	2001	Visual insp during install or repair	Installed after lead ban	N
1-988 SHADOW RIDCEWAY	2 SHADOW RIDGE WAY		N	Р	N	1"	2001	Р	SF	Installation record	Υ	2001	Visual insp during install or repair	Installed after lead ban	N
1868 PIMOW RIGHEM   N   P   N   1'   200; P   SI Insulation record   Y   201; Weal map during small or regain   Insulation record   Y   201; Weal map duri	0 SHADOW RIDGE WAY		N	Р	N	1"	2001	Р	SF	Installation record	Υ	2001	Visual insp during install or repair	Installed after lead ban	N
1866 BIANDOW RIDGE WAY			N	P	N	1"		P			Υ				N
Fig. 14   1900			••	P	• • •			•			<u>.</u>		<u> </u>		N
161 FS ALPOOK REDOK PAY   N			.,,	D				-			-				N
972 SPRONS PRINCIS DR															N N
1909 SPRINKS DR				P D	**			<u> </u>							N N
17.00   17.0				Р							<u>.</u>				
1975 SHOWET FINE			**	Р				•							N
1802 SHOUETE IN			• • • • • • • • • • • • • • • • • • • •	Р	• •			•			<u>.</u>		<u> </u>		N
1609 ELPADETEEN   N   P   N   1"   2002   P   SF   Installation record   V   2002   Visual rings during ristall or repair   Installed after lead ban   1617 ELPADETEEN   N   P   N   1"   2002   P   SF   Installation record   V   2002   Visual rings during ristall or repair   Installed after lead ban   1617 ELPADETEEN   N   P   N   1"   2002   P   SF   Installation record   V   2002   Visual rings during ristall or repair   Installed after lead ban   1618 ELPADETEEN   N   P   N   1"   2002   P   SF   Installation record   V   2002   Visual rings during ristall or repair   Installed after lead ban   1618 ELPADETEEN   N   P   N   1"   2002   P   SF   Installation record   V   2002   Visual rings during ristall or repair   Installed after lead ban   1618 ELPADETEEN   N   P   N   1"   2002   P   SF   Installation record   V   2002   Visual rings during ristall or repair   Installed after lead ban   1618 ELPADETEEN   N   P   N   1"   2002   P   SF   Installation record   V   2002   Visual rings during ristall or repair   Installed after lead ban   1618 ELPADETEEN   N   P   N   1"   2002   P   SF   Installation record   V   2002   Visual rings during ristall or repair   Installed after lead ban   1618 ELPADETEEN   N   P   N   1"   2002   P   SF   Installation record   V   2002   Visual rings during ristall or repair   Installed after lead ban   1618 ELPADETEEN   N   P   N   1"   2002   P   SF   Installation record   V   2002   Visual rings during ristall or repair   Installed after lead ban   1618 ELPADETEEN   N   P   N   1"   2002   P   SF   Installation record   V   2002   Visual rings during ristall or repair   Installed after lead ban   1618 ELPADETEEN   N   P   N   1"   2002   P   SF   Installation record   V   2002   Visual rings during ristall or repair   Installed after lead ban   1618 ELPADETEEN   N   P   N   1"   2005   P   SF   Installation record   V   2002   Visual rings during ristall or repair   Installed after lead ban   1618 ELPADETEEN   N   P   N   1"   2005   P   SF   Installation record   V   2005				Р											N
1012 SILHOUETE IN				P	N			Р		Installation record	Y		Visual insp during install or repair	Installed after lead ban	N
1617 SILHOUETTELN   N	9 SILHOUETTE LN		N	Р	N		2002	Р	SF	Installation record	Υ		Visual insp during install or repair	Installed after lead ban	N
1835 SILHOUETTE IN   N   P   N   1"   2002   P   SF   Installation record   Y   2002   Visual insign during install or repair   Installed after lead ban   1643 SILHOUETTE IN   N   P   N   1"   2002   P   SF   Installation record   Y   2002   Visual insign during install or repair   Installed after lead ban   1643 SILHOUETTE IN   N   P   N   1"   2002   P   SF   Installation record   Y   2002   Visual insign during install or repair   Installed after lead ban   1645 SILHOUETTE IN   N   P   N   1"   2002   P   SF   Installation record   Y   2002   Visual insign during install or repair   Installed after lead ban   1655 SILHOUETTE IN   N   P   N   1"   2002   P   SF   Installation record   Y   2002   Visual insign during install or repair   Installed after lead ban   1655 SILHOUETTE IN   N   P   N   1"   2002   P   SF   Installation record   Y   2002   Visual insign during install or repair   Installed after lead ban   1655 SILHOUETTE IN   N   P   N   1"   2002   P   SF   Installation record   Y   2002   Visual insign during install or repair   Installed after lead ban   1655 SILHOUETTE IN   N   P   N   1"   2005   P   SF   Installation record   Y   2002   Visual insign during install or repair   Installed after lead ban   1655 SILHOUETTE IN   N   P   N   1"   2005   P   SF   Installation record   Y   2005   Visual insign during install or repair   Installed after lead ban   1655 SILHOUETTE IN   N   P   N   1"   2005   P   SF   Installation record   Y   2005   Visual insign during install or repair   Installed after lead ban   1655 SILHOUETTE IN   N   P   N   1"   2005   P   SF   Installation record   Y   2005   Visual insign during install or repair   Installed after lead ban   1655 SILHOUETTE IN   N   P   N   1"   2005   P   SF   Installation record   Y   2005   Visual insign during install or repair   Installed after lead ban   1655 SILHOUETTE IN   N   P   N   1"   2005   P   SF   Installation record   Y   2005   Visual insign during install or repair   Installed after lead ban   1655 SILHOUETTE IN   N   P	2 SILHOUETTE LN		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1640 SLHOUETTE IN	7 SILHOUETTE LN		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1643 SILHOUETTE IN  N P N 1" 2002 P SF Installation record V 2002 Visual ingo during install or repair Installed after lead ban 1688 SILHOUETTE IN  N P N 1" 2002 P SF Installation record V 2002 Visual ingo during install or repair Installed after lead ban 1688 SILHOUETTE IN  N P N 1" 2002 P SF Installation record V 2002 Visual ingo during install or repair Installed after lead ban 1688 SILHOUETTE IN  N P N 1" 2002 P SF Installation record V 2002 Visual ingo during install or repair Installed after lead ban 1688 SILHOUETTE IN  1688 SILHOUETTE IN  N P N 1" 2002 P SF Installation record V 2002 Visual ingo during install or repair Installed after lead ban 1688 SILHOUETTE IN  1688 SILHOUETTE IN  N P N 1" 2005 P SF Installation record V 2002 Visual ingo during install or repair Installed after lead ban 1688 SILHOUETTE IN P N 1" 2005 P SF Installation record V 2002 Visual ingo during install or repair Installed after lead ban 1688 SILHOUETTE IN P N 1" 2005 P SF Installation record V 2005 Visual ingo during install or repair Installed after lead ban 1688 SILHOUETTE IN P N 1" 2005 P SF Installation record V 2005 Visual ingo during install or repair Installed after lead ban 1688 SILHOUETTE IN P N 1" 2005 P SF Installation record V 2005 Visual ingo during install or repair Installed after lead ban 1688 SILHOUETTE IN P N 1" 2005 P SF Installation record V 2005 Visual ingo during install or repair Installed after lead ban 1688 SILHOUETTE IN P N 1" 2005 P SF Installation record V 2005 Visual ingo during install or repair Installed after lead ban 1698 SIRCLARD R N P N 1" 2005 P SF Installation record V 2005 Visual ingo during install or repair Installed after lead ban 1692 SIRCLARD R N P N 1" 2005 P SF Installation record V 2005 Visual ingo during install or repair Installed after lead ban 1692 SIRCLARD R N P N 1" 2005 P SF Installation record V 2005 Visual ingo during install or repair Installed after lead ban 1692 SIRCLARD R N P N 1" 2005 P SF Installation record V 2005 Visual ingo during install or repair Installed after l	5 SILHOUETTE LN		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1643 SILHOUETTE LN	0 SILHOUETTE LN		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1648 ELHOUETTE LN	3 SILHOUETTE LN		N	Р	N	1"	2002	Р	SF	Installation record	Υ		Visual insp during install or repair	Installed after lead ban	N
1668 SILHOUETTE LN	8 SILHOUETTE LN		N	Р	N	1"		Р	SF		Υ				N
1665 SILHOUETTE LN				P				P			Y				N
1686 SILHOUETTE LN				p p				<del>-</del>							N
1908 SINCLAIR DR			**	D				-			-				N
1913 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1918 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1918 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1919 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1919 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1924 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1925 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1932 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1932 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1932 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1932 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1940 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1940 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1951 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1951 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR				г D				<u> </u>			<u> </u>				N N
1913 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1919 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1919 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1924 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1924 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1924 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1925 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1924 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1924 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1924 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1924 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1924 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1924 SINCLAIR DR N P N P N P N P N P N P N P N P N P N				P P				<del>-</del>					1 0 1		
1916 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1924 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1927 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1927 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1927 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1935 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1936 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1940 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1948 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1948 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1951 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1954 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1954 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after				Р											N
1919 SINCLAIR DR  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1924 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1927 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1932 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1932 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1940 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1940 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1948 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1948 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1951 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1956 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR 1958 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR 1958 SINCLAIR DR N P N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR 1958 MOOREN ACRE CT N P N P N 1" 2006 P SF Installation record Y 20				P -											N
1924 SINCLAIR DR  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1932 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1932 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1935 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1940 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1948 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1948 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1951 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1956 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1968 SINCLAIR DR N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1968 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1968 MOOREN ACRE CT N P N 1" 1" 2006 P SF				Р											N
1927 SINCLAIR DR  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1932 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1935 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1940 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1948 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1948 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1951 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1956 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1968 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR 1972 SINCLAIR DR 1972 SINCLAIR DR 1972 SINCLAIR DR 1973 SINCLAIR DR 1974 SINCLAIR DR 1975 SINCLAIR DR 1975 SINCLAIR DR 1975 SINCLAIR DR 1976 SINCLAI			**	Р				-			·				N
1932 SINCLAIR DR  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1935 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1940 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1948 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1951 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR 1958 SINCLAIR DR N P N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR 1972 SINCLAIR DR 1972 SINCLAIR DR 1974 SINCLAIR DR 1975 SINCLAIR DR 1974 SINCLAIR DR 1975 SINCLAIR DR 1975 SINCLAIR DR 1975 SINCLAIR DR 1976 SINCLAIR DR 1976 SINCLAIR DR 1976 SINCLAIR DR 1976 SINCLAIR DR 1978 SINCLAIR DR 19				P	N			Р		Installation record			Visual insp during install or repair	Installed after lead ban	N
1935 SINCLAIR DR  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1940 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1948 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1951 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1959 SINCLAIR DR 1959 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR 1972 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR 1972 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR 1972 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR 1972 SINCLAIR DR 1974 SINCLAIR DR 1975 SINCLAIR DR 1975 SINCLAIR DR 1975 SINCLAIR DR 1976 SINCLAIR DR 1977 SINCLAIR DR 1978 SINCLAIR				Р	N			Р		Installation record			Visual insp during install or repair	Installed after lead ban	N
1940 SINCLAIR DR  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1948 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1951 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1958 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1959 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1964 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N 1974 1974 1974 1974 1974 1974 1974 1974	2 SINCLAIR DR			Р	N			Р		Installation record	Υ		Visual insp during install or repair	Installed after lead ban	N
1948 SINCLAIR DR  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1951 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1956 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1959 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1964 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1964 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1988 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1920 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1932 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1940 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1940 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1940 Mooren 1940	5 SINCLAIR DR		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
1948 SINCLAIR DR  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1951 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1956 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1959 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1964 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1964 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1984 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1994 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1994 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1994 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1994 MOOREN ACRE CT N 1994 N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1995 MOOREN ACRE CT N 1994 N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1995 MOOREN ACRE CT N 1994 N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1995 MOOREN ACRE CT N 1994 MOOREN ACRE CT N	0 SINCLAIR DR		N	Р	N	1"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1951 SINCLAIR DR  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1956 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1959 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1964 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR 1972 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR 1984 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N 1972 MOOREN ACRE CT N 1972 MOOREN ACRE CT N 1973 MOOREN ACRE CT N 1974 MOOREN ACRE CT N 2006 Visual insp during install or repair Installed after lead ban 1974 MOOREN ACRE CT N 2006 Visual insp during install or rep	8 SINCLAIR DR		N	Р	N	1"		Р	SF	Installation record	Υ		Visual insp during install or repair	Installed after lead ban	N
1956 SINCLAIR DR  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1959 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1964 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N 1972 MOOREN ACRE CT N 1984 N 1985 N			N	Р	N			Р			Υ				N
1959 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1964 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT Visual insp during install or repair Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT Visual insp during install or repair			N	Р	N			Р			Υ				N
1964 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR  928 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 SINCLAIR DR  1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 1972 MOOREN ACRE CT N P N 1" 1" 1" 1" 1" 1" 1" 1" 1" 1" 1" 1" 1"				P											N
1972 SINCLAIR DR  N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban 928 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 920 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 920 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 912 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 904 MOOREN ACRE CT Y 2006 Visual insp during install or repair Installed after lead ban 904 MOOREN ACRE CT Y 2006 Visual insp during install or repair Installed after lead ban				P							<u>.</u>				N
928 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 920 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 912 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 914 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 914 MOOREN ACRE CT Y 2006 Visual insp during install or repair Installed after lead ban 914 MOOREN ACRE CT Y 2006 Visual insp during install or repair Installed after lead ban				P											N N
920 MOOREN ACRE CT  N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 912 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 904 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 914 MOOREN ACRE CT N P N 1" 1" 1" 1" 1" 1" 1" 1" 1" 1" 1" 1" 1"				F D				<u> </u>							
912 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban 904 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban				Ρ											N N
904 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban				P											N
			**	Р											N
901 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban				Р							<u>.</u>				N
	MOOREN ACRE CT		N	Р	N			Р		Installation record	Υ		Visual insp during install or repair	Installed after lead ban	N
907 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban	MOOREN ACRE CT		N	Р	N			Р		Installation record	Y		Visual insp during install or repair	Installed after lead ban	N
925 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban	MOOREN ACRE CT		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
933 MOOREN ACRE CT N P N 1" 2006 P SF Installation record Y 2006 Visual insp during install or repair Installed after lead ban	MOOREN ACRE CT		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
3777 SPRING HOLLOW DR N P N 1" 2005 P SF Installation record Y 2005 Visual insp during install or repair Installed after lead ban	7 SPRING HOLLOW DR		N	Р	N	1"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N

3783 SPRING HOLLOW DR		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
3789 SPRING HOLLOW DR		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1101 SPRING LAKE DR		N N	P	N N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1102 SPRING LAKE DR		N N	Р Р	N N	1" 1"	2002	P P	SF SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1103 SPRING LAKE DR		N N	Р Р	N N	1"		P	SF SF	Installation record	Y		Visual insp during install or repair	Installed after lead ban	N N
1104 SPRING LAKE DR		N N	P P	N N	1"	2002	P P	SF SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N N
1108 SPRING LAKE DR 1110 SPRING LAKE DR		N N	P P	N N	1"	2002	P	SF SF	Installation record Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N N
1111 SPRING LAKE DR		N N	P D	N	1"	2002	P P	SF		Y	2002	Visual insp during install or repair	Installed after lead ban Installed after lead ban	N
1114 SPRING LAKE DR		N N	P D	N N	1"	2002	P	SF	Installation record Installation record	Y	2002	Visual insp during install or repair  Visual insp during install or repair	Installed after lead ban	N N
1115 SPRING LAKE DR		N	P D	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1116 SPRING LAKE DR		N	<u>г</u>	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1117 SPRING LAKE DR		N	D D	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1121 SPRING LAKE DR		N	P P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1122 SPRING LAKE DR		N	P	N N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1123 SPRING LAKE DR		N	P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1124 SPRING LAKE DR		N N	P	N N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1125 SPRING LAKE DR		N	P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1131 SPRING LAKE DR		N	P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1132 SPRING LAKE DR		N	Р	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1133 SPRING LAKE DR		N N	P	N N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1136 SPRING LAKE DR		N	P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1139 SPRING LAKE DR		N	P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1137 SPRING LAKE DR		N	P	N	1"	2002	P	SF	Installation record	Υ Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1143 SPRING LAKE DR		N	P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1146 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1147 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1150 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1153 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1157 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1160 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1164 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1169 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1170 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1173 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1172 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1176 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1178 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1182 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1185 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1189 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1186 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1193 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1194 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1195 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
1196 SPRING LAKE DR		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
935 SPRINGFIELD DR		N	Р	N	1"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
943 SPRINGFIELD DR		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
950 SPRINGFIELD DR		N	Р	N	1"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
951 SPRINGFIELD DR		N	Р	N	1"	2005	Р	SF	Installation record	Υ	2005	Visual insp during install or repair	Installed after lead ban	N
959 SPRINGFIELD DR		N	Р	N	1"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
960 SPRINGFIELD DR		N	Р	N	1"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
967 SPRINGFIELD DR		N	Р	N	1"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
968 SPRINGFIELD DR		N	Р	N	1"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
975 SPRINGFIELD DR		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
976 SPRINGFIELD DR		N	P	N	1"	2005	Р	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
983 SPRINGFIELD DR		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
991 SPRINGFIELD DR		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
992 SPRINGFIELD DR		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
999 SPRINGFIELD DR		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1000 SPRINGFIELD DR		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1007 SPRINGFIELD DR		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1008 SPRINGFIELD DR		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1015 SPRINGFIELD DR		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1016 SPRINGFIELD DR		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1023 SPRINGFIELD DR		N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1024 SPRINGFIELD DR	II HAI II WISCONGIN	N N	P	N	1"	2005	P	SF	Installation record	Y	2005	Visual insp during install or repair	Installed after lead ban	N
1294 SUNDOWN CT	U HAUL WISCONSIN		Ρ	N	1"	2007	P	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	N
1300 SUNDOWN CT	U-HAUL OF WISCONSIN	N N	P	N	1"	2007	P P	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	N N
1279 SUNDOWN LN 1283 SUNDOWN LN		N N	P	N N	1" 1"	2007 2007	P P	SF SF	Installation record	Y	2007 2007	Visual insp during install or repair	Installed after lead ban	N N
1297 SUNDOWN LN		N N	P	N N	1"	2007	P	SF SF	Installation record Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	N N
LEGI GUINIJUJVIN LIV		IN	r	IN	1	2007	Ρ	31	ilistaliation record		2007	Visual insp during install or repair	Installed after lead ban	IN

1303 SUNDOWN LN	N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
1304 SUNDOWN LN	N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
1315 SUNDOWN LN	N	Р	N	1"	2007	Р	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	N
1316 SUNDOWN LN	N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
1320 SUNDOWN LN	N	Р	N	1"	2007	Р	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	N
1324 SUNDOWN LN	N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
1327 SUNDOWN LN	N	Р	N	1"	2007	Р	SF	Installation record	Y	2007	Visual insp during install or repair	Installed after lead ban	N
1342 SUNDOWN LN	N	Р	N	1"	2007	Р	SF	Installation record	Υ	2007	Visual insp during install or repair	Installed after lead ban	N
1593 TALUS CIR	N	P	N	1"	1999	P	SF	Installation record	Υ	1999	Visual insp during install or repair	Installed after lead ban	N
1595 TALUS CIR	N	Р	N	1"	1999	P -	SF	Installation record	Υ	1999	Visual insp during install or repair	Installed after lead ban	N
1596 TALUS CIR	N	P	N	1"	1999	P	SF	Installation record	Υ	1999	Visual insp during install or repair	Installed after lead ban	N
1599 TALUS CIR	N	P	N	1"	1999	P	SF	Installation record	Y	1999	Visual insp during install or repair	Installed after lead ban	N
1605 TALUS CIR	N	Р	N	1"	1999	P	SF	Installation record	Y	1999	Visual insp during install or repair	Installed after lead ban	N
1611 TALUS CIR	N	P	N	1"	1999	P	SF	Installation record	Y	1999	Visual insp during install or repair	Installed after lead ban	N
1617 TALUS CIR	N	P	N	1"	1999	P	SF	Installation record	Y	1999	Visual insp during install or repair	Installed after lead ban	N
1620 TALUS CIR	N N	P	N N	1" 1"	1999 1999	P P	SF SF	Installation record	Y	1999	Visual insp during install or repair	Installed after lead ban	N N
1623 TALUS CIR	N N	P		1"	1999	P P	SF SF	Installation record	Y	1999	Visual insp during install or repair	Installed after lead ban	
1629 TALUS CIR	N N	Р Р	N			P P		Installation record	Y	1999	Visual insp during install or repair	Installed after lead ban	N
1635 TALUS CIR	N N	P	N N	1" 1"	1999 1999	Р Р	SF SF	Installation record	Y	1999	Visual insp during install or repair	Installed after lead ban	N
1644 TALUS CIR 1647 TALUS CIR	N N	P P	N N	1"	1999	P P	SF SF	Installation record Installation record	Y	1999 1999	Visual insp during install or repair	Installed after lead ban	N N
1653 TALUS CIR	N N	P D	N N	1"	1999	<u>Р</u>	SF		Y	1999	Visual insp during install or repair	Installed after lead ban Installed after lead ban	N N
1659 TALUS CIR	N N	P D	N	1"	1999	P P	SF	Installation record	Y	1999	Visual insp during install or repair	Installed after lead ban	N N
1665 TALUS CIR	N N	P P	N N	1"	1999	<u>Р</u>	SF SF	Installation record Installation record	Y	1999	Visual insp during install or repair  Visual insp during install or repair	Installed after lead ban	N N
1668 TALUS CIR	N N	D D	N	1"	1999	P	SF	Installation record	Y	1999	Visual insp during install or repair	Installed after lead ban	N N
393 TALUS CT	N N	<u>г</u>	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
396 TALUS CT	N N	D P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N N
411 TALUS CT	N N	P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
427 TALUS CT	N N	P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
432 TALUS CT	N N	P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
441 TALUS CT	N N	Р	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
455 TALUS CT	N	P	N	1"	2002	Р	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
448 TALUS CT	N N	P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
466 TALUS CT	N	P	N	1"	2002	Р	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
473 TALUS CT	N	P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
476 TALUS CT	N	Р	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
487 TALUS CT	N	Р	N	1"	2002	Р	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1585 TIFFANY CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1586 TIFFANY CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1597 TIFFANY CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1598 TIFFANY CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1609 TIFFANY CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1612 TIFFANY CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1617 TIFFANY CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1620 TIFFANY CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1629 TIFFANY CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1630 TIFFANY CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1635 TIFFANY CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1638 TIFFANY CT	N	Р	N	1"	1995	Р	SF	Installation record	Υ	1995	Visual insp during install or repair	Installed after lead ban	N
1764 WILLIAMS GRANT DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1776 WILLIAMS GRANT DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1790 WILLIAMS GRANT DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1808 WILLIAMS GRANT DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1830 WILLIAMS GRANT DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1827 WILLIAMS GRANT DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1842 WILLIAMS GRANT DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1845 WILLIAMS GRANT DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1856 WILLIAMS GRANT DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1871 WILLIAMS GRANT DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1891 WILLIAMS GRANT DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1900 WILLIAMS GRANT DR HEMLOCK CREEK ELEMENTARY	N	Р	N	8"	2006	Р	SCH/DC	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
1927 WILLIAMS GRANT DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1945 WILLIAMS GRANT DR	N	Р	N	1"	2006	Р	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
1946 WILLIAMS GRANT DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1969 WILLIAMS GRANT DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1972 WILLIAMS GRANT DR	N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
908 WINDSONG CT	N	Р	N	1"	2002	Р	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
909 WINDSONG CT	N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
912 WINDSONG CT	N	Р	N	1"	2002	Р	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
		D	N.I.	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
915 WINDSONG CT	N	Р	N			•			· · · · · · · · · · · · · · · · · · ·				
	N N N	P P	N N	1" 1"	2002 2002 2002	P P	SF SF	Installation record Installation record	Y	2002	Visual insp during install or repair Visual insp during install or repair	Installed after lead ban Installed after lead ban	N N

810 WINDSONG WAY		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
811 WINDSONG WAY		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
818 WINDSONG WAY		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
819 WINDSONG WAY		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
825 WINDSONG WAY		N	Р	N	1"	2002	Р	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
826 WINDSONG WAY		N	Р	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
833 WINDSONG WAY		N	P	N	1"	2002	Р	SF	Installation record	Υ	2002	Visual insp during install or repair	Installed after lead ban	N
841 WINDSONG WAY		N	P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
850 WINDSONG WAY		N N	P	N	1"	2002	D	SF	Installation record	· Y	2002	Visual insp during install or repair	Installed after lead ban	N
859 WINDSONG WAY		N	P	N	1"	2002	P	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
867 WINDSONG WAY		N N	P	N	1"	2002	D D	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
875 WINDSONG WAY		N N	<u>Р</u>	N	1"		P P	SF		Y		· • ·		• •
		N N	P D			2002	<u>Р</u>		Installation record	-	2002	Visual insp during install or repair	Installed after lead ban	N
880 WINDSONG WAY			'	N	1"	2002	<u>'</u>	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
883 WINDSONG WAY		N	P	N	1"	2002	Р	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
890 WINDSONG WAY		N	Р	N	1"	2002	Р	SF	Installation record	Y	2002	Visual insp during install or repair	Installed after lead ban	N
1851 WIZARD WAY		N	Р	N	1"	2006	Р	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
1852 WIZARD WAY		N	Р	N	1"	2006	Р	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
1853 WIZARD WAY		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1854 WIZARD WAY		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1860 WIZARD WAY		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1855 WIZARD WAY		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1863 WIZARD WAY		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1867 WIZARD WAY		N	Р	N	1"	2006	Р	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
1868 WIZARD WAY		N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
1869 WIZARD WAY		N N	<u>.</u> Р	N	1"	2006	Р	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
1870 WIZARD WAY		N	Р	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
1871 WIZARD WAY		N N	P	N	1"	2006	D	SF	Installation record	V	2006	Visual insp during install or repair	Installed after lead ban	N
1873 WIZARD WAY		N N	P	N	1"	2006	P P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
1874 WIZARD WAY		N N	Р Р	N N	1"	2006	n n	SF SF		Y V	2006		Installed after lead ban	N N
			<u>Р</u>				<u>Р</u>		Installation record	Y Y		Visual insp during install or repair		
1875 WIZARD WAY		N	•	N	1"	2006	•	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
1877 WIZARD WAY		N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
1879 WIZARD WAY		N	Р	N	1"	2006	Р	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
1881 WIZARD WAY		N	P	N	1"	2006	P	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
1882 WIZARD WAY		N	Р	N	1"	2006	Р	SF	Installation record	Υ	2006	Visual insp during install or repair	Installed after lead ban	N
1883 WIZARD WAY		N	P	N	1"	2006	Р	SF	Installation record	Y	2006	Visual insp during install or repair	Installed after lead ban	N
1587 YELLOW BRIAR DR		N	Р	N	1"	1998	Р	SF	Installation record	Υ	1998	Visual insp during install or repair	Installed after lead ban	N
1596 YELLOW BRIAR DR		N	Р	N	1"	1998	Р	SF	Installation record	Υ	1998	Visual insp during install or repair	Installed after lead ban	N
1597 YELLOW BRIAR DR		N	Р	N	1"	1998	Р	SF	Installation record	Υ	1998	Visual insp during install or repair	Installed after lead ban	N
1602 YELLOW BRIAR DR		N	Р	N	1"	1998	Р	SF	Installation record	Υ	1998	Visual insp during install or repair	Installed after lead ban	N
1607 YELLOW BRIAR DR		N	Р	N	1"	1998	Р	SF	Installation record	Υ	1998	Visual insp during install or repair	Installed after lead ban	N
1610 YELLOW BRIAR DR		N	Р	N	1"	1998	Р	SF	Installation record	Υ	1998	Visual insp during install or repair	Installed after lead ban	N
1615 YELLOW BRIAR DR		N	Р	N	1"	1998	Р	SF	Installation record	Υ	1998	Visual insp during install or repair	Installed after lead ban	N
1618 YELLOW BRIAR DR		N	P	N	1"	1998	Р	SF	Installation record	Υ	1998	Visual insp during install or repair	Installed after lead ban	N
1626 YELLOW BRIAR DR		N	Р	N	1"	1998	Р	SF	Installation record	Υ Υ	1998	Visual insp during install or repair	Installed after lead ban	N
1665 YELLOW BRIAR DR	VHC INC	N	P	N	1 1/2"	1998	P	NONRES	Installation record	· Y	1998	Visual insp during install or repair	Installed after lead ban	N
1680 YELLOW BRIAR DR	ROBINSON INC	N N	P	N	10"	1998	P	NONRES	Installation record	Y	1998	Visual insp during install or repair	Installed after lead ban	N
1101 PISCES PL	ROBINSON INC	N N	P		1"	2012	P P	SF		Y	2012			
		N N	P P	N			•		Installation record	<u> </u>		Visual insp during install or repair	Installed after lead ban	N
1100 PISCES PL			•	N	1"	2012	P	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
1103 PISCES PL		N	P	N	1"	2012	P	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
1104 PISCES PL		N	P	N	1"	2012	P	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
1107 PISCES PL		N	P	N	1"	2012	P	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
1108 PISCES PL		N	Р	N	1"	2012	Р	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
1111 PISCES PL		N	Р	N	1"	2012	Р	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
1112 PISCES PL		N	Р	N	1"	2012	Р	SF	Installation record	Υ	2012	Visual insp during install or repair	Installed after lead ban	N
1115 PISCES PL		N	Р	N	1"	2012	Р	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
1116 PISCES PL		N	Р	N	1"	2012	Р	SF	Installation record	Υ	2012	Visual insp during install or repair	Installed after lead ban	N
1119 PISCES PL		N	Р	N	1"	2012	Р	SF	Installation record	Υ	2012	Visual insp during install or repair	Installed after lead ban	N
1120 PISCES PL		N	Р	N	1"	2012	Р	SF	Installation record	Υ	2012	Visual insp during install or repair	Installed after lead ban	N
1123 PISCES PL		N	Р	N	1"	2012	Р	SF	Installation record	Υ	2012	Visual insp during install or repair	Installed after lead ban	N
1128 PISCES PL		N	P	N	1"	2012	Р	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
1139 PISCES PLACE		N N	P	N	1"	2012	Р	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
1132 PISCES PL		N	Р	N	1"	2012	P	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
1143 PISCES PL		N	P	N	1"	2012	P	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
1136 PISCES PLACE		N N	P	N	1"	2012	Р	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
1140 PISCES PLACE		N N	P P		1"	2012	<u>Р</u>	SF SF		Y	2012			N
			Р Р	N			Р Р		Installation record			Visual insp during install or repair	Installed after lead ban	
1144 PISCES PL		N	•	N	1"	2012		SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
1148 PISCES PL		N	P	N	1"	2012	P	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
1147 PISCES PL		N	P	N	1"	2012	P	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
1152 PISCES PL		N	P	N	1"	2012	P	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
1151 PISCES PL		N	Р	N	1"	2012	Р	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
1156 PISCES PL		N	Р	N	1"	2012	Р	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
1155 PISCES PL		N	Р	N	1"	2012	Р	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N

1160 PISCES PL	N	Р	N	1"	2012	Р	SF	Installation record	Υ	2012	Visual insp during install or repair	Installed after lead ban	N
159 PISCES PL	N	Р	N	1"	2012	Р	SF	Installation record	Υ	2012	Visual insp during install or repair	Installed after lead ban	N
164 PISCES PL	N	Р	N	1"	2012	P	SF	Installation record	Υ	2012	Visual insp during install or repair	Installed after lead ban	N
163 PISCES PL	N	Р	N	1"	2012	Р	SF	Installation record	Υ	2012	Visual insp during install or repair	Installed after lead ban	N
166 PISCES PL	N	P	N	1"	2012	Р	SF	Installation record	Υ	2012	Visual insp during install or repair	Installed after lead ban	N
167 PISCES PL	N	Р	N	1"	2012	Р	SF	Installation record	Υ	2012	Visual insp during install or repair	Installed after lead ban	N
673 ANDROMEDA DR	N	Р	N	1"	2015	P	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
683 ANDROMEDA DR	N	Р	N	1"	2015	Р	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
83 HOKS RIDGE LN	N	Р	N	1"	2012	Р	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
30 HOKS RIDGE LN	N	P	N	1"	2012	P	SF	Installation record	Υ	2012	Visual insp during install or repair	Installed after lead ban	N
84 HOKS RIDGE LN	N	P	N	1"	2012	P	SF	Installation record	Υ	2012	Visual insp during install or repair	Installed after lead ban	N
37 HOKS RIDGE LN	N	P	N	1"	2012	P	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
38 HOKS RIDGE LN	N	P	N	1"	2012	P	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
992 HOKS RIDGE LN	N N	P	N	1"	2012	P	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
45 HOKS RIDGE LN	N	P	N	1"	2012	P	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
46 HOKS RIDGE LN	N	P P	N	1" 1"	2012	P	SF SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
91 HOKS RIDGE LN	N	P P	N		2012	<u>Р</u>		Installation record		2012	Visual insp during install or repair	Installed after lead ban	N
53 HOKS RIDGE LN	N N	P	N	1"	2012	<u>Р</u>	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N N
154 HOKS RIDGE LN 199 HOKS RIDGE LN	N N	P	N N	1" 1"	2012 2012	P P	SF SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N N
99 HONS RIDGE LN 162 HOKS RIDGE LN	N N	P P	N N	1"	2012	Р D	SF SF	Installation record Installation record	Y Y	2012	Visual insp during install or repair	Installed after lead ban Installed after lead ban	N N
61 HOKS RIDGE LN	N N	P	N N	1"	2012	<u>Р</u>	SF	Installation record	Y	2012	Visual insp during install or repair Visual insp during install or repair	Installed after lead ban	N
169 HOKS RIDGE LN	N	P D	N N	1"	2012	<u>Р</u>	SF	Installation record		2012	Visual insp during install or repair	Installed after lead ban	N
000 HOKS RIDGE LIN	N N	P P	N N	1"	2012	P P	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N N
70 HOKS RIDGE LN	N	D D	N N	1"	2012	D D	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
777 HOKS RIDGE LN	N	P	N	1"	2012	P	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
1011 HOKS RIDGE LN	N N	P	N	1"	2012	P	SF	Installation record	V	2012	Visual insp during install or repair	Installed after lead ban	N
1008 HOKS RIDGE LN	N	P	N	1"	2012	P	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
017 HOKS RIDGE LN	N N	P	N	1"	2012	P	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
016 HOKS RIDGE LN	N	Р	N	1"	2012	Р	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
023 HOKS RIDGE LN	N N	<u>.</u> Р	N	1"	2012	 P	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
024 HOKS RIDGE LN	N N	P	N	1"	2012	P	SF	Installation record	Y	2012	Visual insp during install or repair	Installed after lead ban	N
139 COSMOS WAY	N	P	N	1"	2013	P	SF	Installation record	Y	2013	Visual insp during install or repair	Installed after lead ban	N
143 COSMOS WY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
144 COSMOS WAY	N	P	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
147 COSMOS WAY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
148 COSMOS WAY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
151 COSMOS WAY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
152 COSMOS WAY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
155 COSMOS WY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
156 COSMOS WAY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
159 COSMOS WAY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
160 COSMOS WAY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
163 COSMOS WAY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
164 COSMOS WAY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
1167 COSMOS WAY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
1168 COSMOS WAY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
1172 COSMOS WAY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
1173 COSMOS WAY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
1176 COSMOS WAY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
1177 COSMOS WAY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
180 COSMOS WAY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
181 COSMOS WAY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
185 COSMOS WAY	N	Р	N	1"	2013	Р	SF	Installation record	Υ	2013	Visual insp during install or repair	Installed after lead ban	N
686 ANDROMEDA DR	N	P	N	1"	2015	P	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
687 ANDROMEDA DR	N	Р	N	1"	2015	Р	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
2690 ANDROMEDA DR	N	Р	N	1"	2015	Р	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
691 ANDROMEDA DR	N	P	N	1"	2015	P	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
694 ANDROMEDA DR	N N	P	N	1"	2015	P	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
695 ANDROMEDA DR	N	P	N	1"	2015	P	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
698 ANDROMEDA DR	N	P	N	1"	2015	P	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
699 ANDROMEDA DR	N	P	N	1"	2015	P	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
703 ANDROMEDA DR	N	P	N	1"	2015	P	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N N
188 COSMOS WY	N	P	N	1"	2013	P	SF	Installation record	Y	2013	Visual insp during install or repair	Installed after lead ban	N
2707 ANDROMEDA DR	N	P	N	1"	2015	P	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
2711 ANDROMEDA CT	N	P	N	1"	2015	P	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
2715 ANDROMEDA CT	N	P	N	1"	2015	P	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
189 COSMOS WY	N	P	N	1"	2013	P	SF	Installation record	Y	2013	Visual insp during install or repair	Installed after lead ban	N
2719 ANDROMEDA CT	N N	P	N	1"	2015	P	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
2722 ANDROMEDA CT	N N	P	N	1"	2015	P	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
2723 ANDROMEDA CT	N	P	N	1"	2015	P	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
2724 ANDROMEDA CT	N	Р	N	1"	2015	Р	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N

Control   Cont														
Mathematical Content of the conten	2726 ANDROMEDA CT	N	Р	N	1"	2015	Р	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
Management   Man	2727 ANDROMEDA CT	N	Р	N	1"	2015	Р	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
March   Marc	901 RAVEN CLAW CT	N	Р	N	1"	2014	Р	SF	Installation record	Υ	2014	Visual insp during install or repair	Installed after lead ban	N
Proceedings	902 RAVEN CLAW CT	N	Р	N	1"	2014	Р	SF	Installation record	Υ	2014	Visual insp during install or repair	Installed after lead ban	N
Proceedings	906 RAVEN CLAW CT	N	Р	N	1"	2014	Р	SF	Installation record	Y	2014	Visual insp during install or repair	Installed after lead ban	N
Part   Career   Car		N	Р	N			Р			Υ				N
Second Column   Second Colum		**	D				D			· v		<u> </u>		
March   Marc							Р.			I		· • · · · ·		
Part			•				P -			Y				
98 MONTANIES   1							Р			Y				
September   1			Р	N			Р		Installation record	Υ		Visual insp during install or repair	Installed after lead ban	N
The Control of Contr	915 RAVEN CLAW CT	N	Р	N	1"	2014	Р	SF	Installation record	Υ	2014	Visual insp during install or repair	Installed after lead ban	N
Mathematical   Math	2146 ROWLING RD	N	Р	N	1"	2014	Р	SF	Installation record	Υ	2014	Visual insp during install or repair	Installed after lead ban	N
Teacher   Teac	2150 ROWLING RD	N	Р	N	1"	2014	Р	SF	Installation record	Υ	2014	Visual insp during install or repair	Installed after lead ban	N
Mathematical   Math	2154 ROWLING RD	N	Р	N	1"	2014	Р	SF	Installation record	Υ	2014	Visual insp during install or repair	Installed after lead ban	N
18   18   18   18   18   18   18   18		N	P	N			P			Y				
Part							D							
Mathematical   Math			· · · · · · · · · · · · · · · · · · ·							•				
Part				IN						Y		· • ·		
SERFORMERS   N		**	'	N			•		Installation record	Υ		Visual insp during install or repair		N
19   15   15   15   15   15   15   15	2176 ROWLING RD		Р	N		2014	Р		Installation record	Υ		Visual insp during install or repair	Installed after lead ban	N
STR PROMISSION   P	2185 ROWLING RD	N	Р	N	1"	2014	Р	SF	Installation record	Υ	2014	Visual insp during install or repair	Installed after lead ban	N
19.   19.	2181 ROWLING RD	N	Р	N	1"	2014	Р	SF	Installation record	Υ	2014	Visual insp during install or repair	Installed after lead ban	N
2. P.	2177 ROWLING RD	N	Р	N	1"	2014	Р	SF	Installation record	Υ	2014	Visual insp during install or repair	Installed after lead ban	N
1986   Part			Р	N			P			Y				
Part			<u> </u>									<u> </u>		
19   19   19   19   19   19   19   19		**	•	**						•				
Management   Man														
See Form			'							Υ				
2007 GRINGOTTS WY   N   P   N   1   2016   P   S   10   10   10   10   10   10   10			<u>'</u>				'			Y				
222   222   222   222   222   223	2145 ROWLING RD		Р	N		2014	Р		Installation record	Υ	2014	Visual insp during install or repair	Installed after lead ban	N
1971   1971	2267 GRINGOTTS WY	N	Р	N	1"	2015	Р	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
221 CHANGROTTS WY	2268 GRINGOTTS WY	N	Р	N	1"	2015	Р	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
222 GRRAGOTTS WY   N   P   N   1   2015   P   S   Institution record   Y   2015   Vaul angular greated in recoast   Insulated after had been   N   2025 GRRAGOTTS WY   N   P   N   1   2015   P   S   Institution record   Y   2015   Vaul angular greated   recognition and recommendation   N   2025 GRRAGOTTS WY   N   N   P   N   1   2015   P   S   Institution record   Y   2015   Vaul angular greated   recognition and recognition   N   P   N   1   2015   P   S   Institution record   Y   2015   Vaul angular greated   recognition   N   Value   N	2271 GRINGOTTS WY	N	Р	N	1"	2015	Р	SF	Installation record	Υ				N
2275 GREAGOTTS WY   N   P   N   1   2015   P   5   Installation record   V   2015   What leng during install or repeat   Installated after read base   N   2275 GREAGOTTS WY   N   P   N   N   P   N   N   P   N   N			D				D			V				
2200 GRANGOTTS WY   N   P   N   1'   2015   P   St Installation record   Y   2015   Visual rings during maturing part   installed after lead bas   N   2000 GRANGOTTS WY   N   P   N   1'   2015   P   St Installation record   Y   2015   Visual rings during maturing part   installed after lead bas   N   2000 GRANGOTTS WY   N   P   N   N   P   N   N   P   ST   Installation record   Y   2015   Visual rings during maturing record introduction and   N   N   P   N   N   P   VISUAL   VISUAL RINGS DURING DURING ST   VISUAL RINGS DURING ST   VISUAL		**	· · · · · · · · · · · · · · · · · · ·	**						•				
2200 GRAGOTTS WY   N   P   N   1"   2015   P   Set Installation record   Y   2015   Valual roug during match or egain   Installation after code both   N   P   N   1"   2015   P   Set Installation record   Y   2015   Valual roug during match or egain   Installation after code both   N   P   N   1"   2015   P   Set Installation record   Y   2015   Valual roug during match or egain   Installation after code both   N   P   N   1"   2015   P   Set Installation record   Y   2015   Valual roug during match or egain   Installation after code both   N   P   N   1"   2015   P   Set Installation record   Y   2015   Valual roug during match or egain   Installation after code both   N   P   N   1"   2015   P   Set Installation record   Y   2015   Valual roug during match or egain   Installation after code both   N   P   N   1"   2015   P   Set Installation record   Y   2015   Valual roug during match or egain   Installation after code both   N   P   N   1"   2015   P   Set Installation record   Y   2015   Valual roug during match or egain   Installation after code both   N   P   N   1"   2015   P   Set Installation record   Y   2015   Valual roug during match or egain   Installation after code both   N   P   N   1"   2015   P   Set Installation record   Y   2015   Valual roug during match or egain   Installation after code both   N   P   N   1"   2015   P   Set Installation record   Y   2015   Valual roug during match or egain   Installation after code both   N   P   N   1"   2015   P   Set Installation record   Y   2015   Valual roug during match or egain   Installation after code both   N   P   N   N   1"   2015   P   Set Installation record   Y   2015   Valual roug during match or egain   Installation after code both   N   P   N   N   1"   2015   P   Set Installation record   Y   2015   Valual roug during match or egain   Installation after code both   N   P   N   N   1"   2015   P   Set Installation record   Y   2015   Valual roug during match or egain   Installation after code both   N   N   N   N   N   N   N   N   N														
2800 GRANGOTTS WY			<u> </u>							•				
2230 GRANGOTTS WY   N   P   N   1"   2015   P   SF   Installation encoral   Y   2015   Vasual integrating in partial or repair   Installed after lead but   N   2230 GRANGOTTS WY   N   P   N   1"   2015   P   SF   Installation encord   Y   2015   Vasual integrating in partial granting after lead but   N   2230 GRANGOTTS WY   N   P   N   1"   2015   P   SF   Installation encord   Y   2015   Vasual integrating in partial granting after lead but   N   N   P   N   1"   2015   P   SF   Installation encord   Y   2015   Vasual integrating in partial granting after lead but   N   N   P   N   1"   2015   P   SF   Installation encord   Y   2015   Vasual integrating in partial granting after lead but   N   Value   Valu	2279 GRINGOTTS WY	N	Р	N		2015	Р		Installation record	Y		Visual insp during install or repair	Installed after lead ban	N
2224 GRINGOTTS WY   N   P   N   1'   2015   P   SF   Installation record   Y   2015   Visual inspiring natural crepair   Installed after lead but N   N   P   N   1'   2015   P   SF   Installation record   Y   2015   Visual inspiring natural crepair   Installed after lead but N   N   P   N   1'   2015   P   SF   Installation record   Y   2015   Visual inspiring natural crepair   Installed after lead but N   N   P   N   1'   2015   P   SF   Installation record   Y   2015   Visual inspiring natural crepair   Installed after lead but N   N   P   N   1'   2015   P   SF   Installation record   Y   2015   Visual inspiring natural crepair   Installed after lead but N   N   P   N   1'   2015   P   SF   Installation record   Y   2015   Visual inspiring natural crepair   Installed after lead but N   N   P   N   1'   2015   P   SF   Installation record   Y   2015   Visual inspiring natural crepair   Installed after lead but N   N   P   N   1'   2015   P   SF   Installation record   Y   2015   Visual inspiring natural crepair   Installed after lead but N   N   P   N   1'   2015   P   SF   Installation record   Y   2015   Visual inspiring natural crepair   Installed after lead but N   N   P   N   1'   2015   P   SF   Installation record   Y   2015   Visual inspiring natural crepair   Installed after lead but N   N   P   N   1'   2015   P   SF   Installation record   Y   2015   Visual inspiring natural crepair   Installed after lead but N   N   P   N   1'   2015   P   SF   Installation record   Y   2015   Visual inspiring natural crepair   Installed after lead but N   N   P   N   1'   2015   P   SF   Installation record   Y   2015   Visual inspiring natural crepair   Installed after lead but N   N   P   N   1'   2015   P   SF   Installation record   Y   2015   Visual inspiring natural crepair   Installed after lead but N   N   P   N   1'   2015   P   SF   Installation record   Y   2015   Visual inspiring natural crepair   Installed after lead but N   N   P   N   1'   2015   P   SF   Installation record   Y   2015   Visual i	2280 GRINGOTTS WY	N	Р	N	1"	2015	Р	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
2257 CRANGOTTS MY	2283 GRINGOTTS WY	N	Р	N	1"	2015	Р	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
220 GRANCOTTS MY	2284 GRINGOTTS WY	N	Р	N	1"	2015	Р	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
2292 CRINDOTTS WY		N	P	N			P			Υ				N
2226 GRINGOTTS WY			P				P			V				
2995 GRINGOTTS WY			<u> </u>							•				
2929 GRNOOTIS WY		• • • • • • • • • • • • • • • • • • • •	<u> </u>				Р .			Y				
2820 GRINOOTIS WY		•••	· · · · · · · · · · · · · · · · · · ·	•••			Р			Y				••
2806 RRINKOTTS WY  N P N 1 <sup>1</sup> 2015 P S <sup>1</sup> Installation record V 2015 Vsual rings during install or repair Installed after lead ban N 2007 RRINKOTTS WY N N P N N P N N 1 <sup>1</sup> 2015 P S <sup>2</sup> Installation record V 2015 Vsual rings during install or repair Installed after lead ban N 2007 RRINKOTTS WY N N P N N P N N 1 <sup>1</sup> 2015 P S <sup>2</sup> Installation record V 2015 Vsual rings during install or repair Installed after lead ban N 2314 GRINKOTTS WY N N P N N P N N 1 <sup>1</sup> 2015 P S <sup>2</sup> Installation record V 2015 Vsual rings during install or repair Installed after lead ban N 2314 GRINKOTTS WY N N P N N P N N P N N P N N P N N P N N P N N P N N P N N P N R P N R P N R R S <sup>2</sup> Installation record V 2015 Vsual rings during install or repair Installed after lead ban N R 2315 GRINKOTTS WY N N P N R R S <sup>2</sup> Installation record V 2015 Vsual rings during install or repair Installed after lead ban N R R S <sup>2</sup> Installation record V 2015 Vsual rings during install or repair Installed after lead ban N R R R R R R R R R R R R R R R R R R									Installation record	Y			Installed after lead ban	
2006 GRNOOTTS WY	2302 GRINGOTTS WY	N	Р	N	1"	2015	Р	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
297 GRINGOTTS WY   N   P   N   1	2303 GRINGOTTS WY	N	Р	N	1"	2015	Р	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
2375 GRINGOTTS WY   N   P   N   1	2306 GRINGOTTS WY	N	Р	N	1"	2015	Р	SF	Installation record	Y	2015	Visual insp during install or repair	Installed after lead ban	N
2319 GRINGOTTS WY		N	P	N			P			Υ				
2314 GRINGOTTS WY  N P N 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair 2315 GRINGOTTS WY  N P N 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair 2316 GRINGOTTS WY  N P N 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair 2316 GRINGOTTS WY  N P N 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair 2317 CRIVING RD  N P N 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair 2318 CRIVING RD  N P N 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair 2318 CRIVING RD  N P N 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair 2318 CRIVING RD  N P N 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair 2318 CRIVING RD  N P N 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair 2318 CRIVING RD  N P N 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair 2318 CRIVING RD  N P N 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair 2318 CRIVING RD  N P N 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair 2318 CRIVING RD  N P N 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair 2318 CRIVING RD  N P N 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair 2318 CRIVING RD  N P N 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair 2318 CRIVING RD  N P N 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair 2318 CRIVING RD  N P N 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair 2318 CRIVING RD  N P N 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair 2318 CRIVING RD  N P N 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair Installed after lead ban N 1 1º 2015 P 5F Installation record V 2015 Visual insp during install or repair Installed after lead ban N 1 1º			D				D					· • · · · ·		
2314 GRINGOTTS WY   N   P   N   1"   2015   P   SF   Installation record   Y   2015   Visual insp during install or regair   Installed after lead ban   N   N   P   N   1"   2015   P   SF   Installation record   Y   2015   Visual insp during install or regair   Installed after lead ban   N   N   P   N   1"   2015   P   SF   Installation record   Y   2015   Visual insp during install or regair   Installed after lead ban   N   N   P   N   N   1"   2015   P   SF   Installation record   Y   2015   Visual insp during install or repair   Installed after lead ban   N   N   N   P   N   N   N   P   N   N			•				Р.			•				
2315 GRINGOTTS WY  N P N 1 <sup>1</sup> 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2193 ROWLING RD N P N 1 <sup>2</sup> 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2201 ROWLING RD N P N 1 <sup>2</sup> 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2201 ROWLING RD N P N 1 <sup>2</sup> 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2201 ROWLING RD N P N 1 <sup>2</sup> 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N 2201 ROWLING RD N P N 1 <sup>2</sup> 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N 2194 ROWLING RD N P N 1 <sup>2</sup> 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N 2194 ROWLING RD N P N 1 <sup>2</sup> 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N 2194 ROWLING RD N P N 1 <sup>2</sup> 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N 2194 ROWLING RD N P N 1 <sup>2</sup> 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N 2194 ROWLING RD N P N 1 <sup>2</sup> 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N 2024 ROWLING RD N P N 1 <sup>2</sup> 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N 2024 ROWLING RD N P N 1 <sup>2</sup> 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N 2024 ROWLING RD N P N 1 <sup>2</sup> 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N N P N 1 <sup>2</sup> 2016 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N N P N 1 <sup>2</sup> 2016 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N N P							P 2							
2193 ROWLING RD			· · · · · · · · · · · · · · · · · · ·							Y				
297 ROWLING RD							Г			Υ				
2201 ROWLING RD   N   P   N   1"   2015   P   SF   Installation record   Y   2015   Visual insp during install or repair   Installed after lead ban   N   P   N   1"   2015   P   SF   Installation record   Y   2015   Visual insp during install or repair   Installed after lead ban   N   N   P   N   1"   2015   P   SF   Installation record   Y   2015   Visual insp during install or repair   Installed after lead ban   N   N   P   N   1"   2015   P   SF   Installation record   Y   2015   Visual insp during install or repair   Installed after lead ban   N   N   N   P   N   1"   2015   P   SF   Installation record   Y   2015   Visual insp during install or repair   Installed after lead ban   N   N   N   P   N   1"   2015   P   SF   Installation record   Y   2015   Visual insp during install or repair   Installed after lead ban   N   N   N   P   N   1"   2015   P   SF   Installation record   Y   2015   Visual insp during install or repair   Installed after lead ban   N   N   N   N   P   N   1"   2015   P   SF   Installation record   Y   2015   Visual insp during install or repair   Installed after lead ban   N   N   N   N   P   N   1"   2015   P   SF   Installation record   Y   2015   Visual insp during install or repair   Installed after lead ban   N   N   N   P   N   1"   2015   P   SF   Installation record   Y   2015   Visual insp during install or repair   Installed after lead ban   N   N   N   P   N   1"   2015   P   SF   Installation record   Y   2015   Visual insp during install or repair   Installed after lead ban   N   N   N   P   N   1"   2015   P   SF   Installation record   Y   2015   Visual insp during install or repair   Installed after lead ban   N   N   N   P   N   1"   2017   P   SF   Installation record   Y   2015   Visual insp during install or repair   Installed after lead ban   N   N   N   P   N   1"   2017   P   SF   Installation record   Y   2017   Visual insp during install or repair   Installed after lead ban   N   N   N   P   N   1"   2017   P   SF   Installation record   Y   2017   Visual i			Р	N			Р		Installation record	Υ		Visual insp during install or repair	Installed after lead ban	N
2208 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2190 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2190 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2190 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2202 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2202 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2202 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2202 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2202 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2017 ROWLING RD  N P N 1" 2017 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2017 ROWLING RD  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 2017 ROWLING RD  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 2017 ROWLING RD  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after	2197 ROWLING RD	N	Р	N	1"	2015	P	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
2208 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2190 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2190 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2190 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2202 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2202 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2202 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2202 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2202 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2017 ROWLING RD  N P N 1" 2017 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2017 ROWLING RD  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 2017 ROWLING RD  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 2017 ROWLING RD  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after	2201 ROWLING RD	N	Р	N	1"	2015	Р	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
2198 ROWLING RD   N   P   N   1"   2015   P   SF   Installation record   Y   2015   Visual insp during install or repair   Installed after lead ban   N   N   P   N   N   N   P   N   N   N		N	Р	N			Р	SF		Υ				N
2190 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2194 ROWLING RD N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N P 2006 ROWLING RD N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N P N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N P N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N P N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N P N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N P N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N P N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N N P N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N N P N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N N P N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N N P N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N N N P N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N N P N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N N N P N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N N N P N P N 1" 2017 P SF Installation record Y 2017			Р				Р			Υ				
2194 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2198 ROWLING RD N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N P N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N P R N P N P N P N P N P N P N P N P			<u> </u>				D			•				
198 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2020 ROWLING RD N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2020 ROWLING RD N P N P N P N P N P N P N P N P N P N														
2202 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2206 ROWLING RD N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N P N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N P N P N P N P N P N P N P N P N P		**	<u> </u>							•		<u> </u>		
2206 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2210 ROWLING RD N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2214 ROWLING RD N P N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N N P N P N P N P N P N P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N P N P N P N P N P N P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N P N P N P N P N P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N P N P N P N P N P N P N P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N P N P N P N P N P N P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N P N P N P N P N P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N P N P N P N P N P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N P N P N P N P N P N P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N P N P N P N P N P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N P N P N P N P N P N P N P N P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N P N P N P N P N P N P SF Installation record Y 2017 Visual insp during install or repair Inst		• • • • • • • • • • • • • • • • • • • •	<u> </u>							Υ				
2210 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 2214 ROWLING RD N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 1771 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1773 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1775 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1777 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1779 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1778 APPLEWOOD DR N 1779 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1781 APPLEWOOD DR N N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1784 APPLEWOOD DR N N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1785 APPLEWOOD DR N N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1786 APPLEWOOD DR N N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1786 APPLEWOOD DR N N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1788 APPLEWOOD DR N N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1789 APPLEWOOD DR N N P N N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N N N N N N N N N N N N N N N N N N			· · · · · · · · · · · · · · · · · · ·	N			Р		Installation record	Y		Visual insp during install or repair	Installed after lead ban	N
2214 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 1771 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1773 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1775 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1777 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1779 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1781 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1784 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1785 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1785 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1786 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1788 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1789 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1789 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1789 APPLEWOOD DR N 1780 APPLEWOOD DR N 178			Р	N			Р		Installation record	Υ		Visual insp during install or repair	Installed after lead ban	N
2214 ROWLING RD  N P N 1" 2015 P SF Installation record Y 2015 Visual insp during install or repair Installed after lead ban N 1771 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1773 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1775 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1777 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1779 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1781 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1784 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1785 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1785 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1786 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1788 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1789 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1789 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1789 APPLEWOOD DR N 1780 APPLEWOOD DR N 178	2210 ROWLING RD	N	Р	N	1"	2015	Р	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
1771 APPLEWOOD DR  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1773 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1775 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1774 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1779 APPLEWOOD DR N 1780 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1781 APPLEWOOD DR N N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1781 APPLEWOOD DR N 1785 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1784 APPLEWOOD DR N 1785 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1788 APPLEWOOD DR N 1789 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1789 APPLEWOOD DR N N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1789 APPLEWOOD DR N N N N N N N N N N N N N N N N N N N	2214 ROWLING RD	N	Р	N	1"	2015	Р	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
1773 APPLEWOOD DR  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1775 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1777 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1779 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1781 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1785 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1785 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1789 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1789 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N N N N N N N N N N N N N N N N N N		N	Р	N			Р			Υ				N
1775 APPLEWOOD DR  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1777 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1779 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1781 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1785 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1785 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N 1789 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N N N N N N N N N N N N N N N N N N			•				D			٧		<u> </u>		
1777 APPLEWOOD DR  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1779 APPLEWOOD DR  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1781 APPLEWOOD DR  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1785 APPLEWOOD DR  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1785 APPLEWOOD DR  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1789 APPLEWOOD DR  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N							n n							
1779 APPLEWOOD DR  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N  1781 APPLEWOOD DR  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N  1785 APPLEWOOD DR  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N  1789 APPLEWOOD DR  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N  1789 APPLEWOOD DR  N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N			· · · · · · · · · · · · · · · · · · ·							•				
1781 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1785 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1789 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N N N N P N N N N N N N N N N N N N N			<u>'</u>							Y				
1785 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N 1789 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N	1779 APPLEWOOD DR		Р	N			Р		Installation record	Y		Visual insp during install or repair	Installed after lead ban	N
1789 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N	1781 APPLEWOOD DR	N	Р	N	1"	2017	P	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1789 APPLEWOOD DR N P N 1" 2017 P SF Installation record Y 2017 Visual insp during install or repair Installed after lead ban N	1785 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
		N	Р	N	1"	2017	Р	SF		Υ				N
			Р				Р			Υ				
		IN		H	-	2017		31			2017			

4703 APPLEWOOD DD	NI NI	P	NI NI	4"	2017	D	CF	Installation record	٧	2017	Visualisas durina install an reneir	Locate Hand of the related have	
1793 APPLEWOOD DR 1795 APPLEWOOD DR	N N	Р Р	N N	1" 1"	2017 2017	Р Р	SF SF	Installation record Installation record	Y V	2017 2017	Visual insp during install or repair Visual insp during install or repair	Installed after lead ban Installed after lead ban	N N
1797 APPLEWOOD DR	N N	P	N	1"	2017	P	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1115 APPLEWOOD DR	N	Р	N	1"	2017	<u>.</u> Р	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1117 APPLEWOOD DR	N	P	N	1"	2017	P	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1119 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1121 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1123 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1125 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1127 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1129 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1131 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1133 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1135 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1137 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1139 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1141 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1140 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1138 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1136 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1132 APPLEWOOD DR	N	P	N	1"	2017	Р	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1130 APPLEWOOD DR	N	P	N	1"	2017	P	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1128 APPLEWOOD DR	N	P	N	1"	2017	P	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1126 APPLEWOOD DR	N	P	N	1"	2017	P	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1124 APPLEWOOD DR	N	P	N	1"	2017	P	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1122 APPLEWOOD DR	N	P	N	1"	2017	P	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1120 APPLEWOOD DR	N	P P	N	1"	2017	P	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1796 APPLEWOOD DR	N	'	N	1"	2017	Р	SF	Installation record	•	2017	Visual insp during install or repair	Installed after lead ban	N
1017 CIDER DR	N	P P	N N	1"	2017	P P	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1019 CIDER DR	N	•	N	1"	2017	P D	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1021 CIDER DR	N N	P P	N N	1"	2017	P P	SF SF	Installation record	V	2017	Visual insp during install or repair	Installed after lead ban	N
1023 CIDER DR 1025 CIDER DR	N N	P	N N	1" 1"	2017 2017	P D	SF SF	Installation record	Y	2017 2017	Visual insp during install or repair	Installed after lead ban	N N
1027 CIDER DR	N N	P P	N N	1"	2017	<u>Р</u>	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban Installed after lead ban	N
1027 CIDER DR	N N	P	N N	1"	2017	P D	SF	Installation record Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1029 CIDER DR 1033 CIDER DR	N N	Р	N N	1"	2017	P P	SF SF	Installation record	Y Y	2017	Visual insp during install or repair Visual insp during install or repair	Installed after lead ban	N N
1037 CIDER DR	N N	P	N	1"	2017	P	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1034 CIDER DR	N N	P P	N	1"	2017	P P	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1030 CIDER DR	N N	P	N	1"	2017	D D	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1026 CIDER DR	N	Р	N	1"	2017	Р	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1024 CIDER DR	N	P	N	1"	2017	P	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1022 CIDER DR	N	Р	N	1"	2017	Р	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1020 CIDER DR	N	P	N	1"	2017	P	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1018 CIDER DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1016 CIDER DR	N	Р	N	1"	2017	Р	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1015 NUTMEG DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1017 NUTMEG DR	N	Р	N	1"	2017	Р	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1019 NUTMEG DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1021 NUTMEG DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1023 NUTMEG DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1027 NUTMEG DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1022 NUTMEG DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1020 NUTMEG DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1016 NUTMEG DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1014 NUTMEG DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1780 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Y	2017	Visual insp during install or repair	Installed after lead ban	N
1776 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1774 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
1772 APPLEWOOD DR	N	Р	N	1"	2017	Р	SF	Installation record	Υ	2017	Visual insp during install or repair	Installed after lead ban	N
2138 DRAGON CT	N	Р	N	1"	2018	Р	SF	Installation record	Υ	2018	Visual insp during install or repair	Installed after lead ban	N
2136 DRAGON CT	N	Р	N	1"	2018	Р	SF	Installation record	Y	2018	Visual insp during install or repair	Installed after lead ban	N
2134 DRAGON CT	N	Р	N	1"	2018	Р	SF	Installation record	Y	2018	Visual insp during install or repair	Installed after lead ban	N
2132 DRAGON CT	N	Р	N	1"	2018	Р	SF	Installation record	Υ	2018	Visual insp during install or repair	Installed after lead ban	N
2130 DRAGON CT	N	Р	N	1"	2018	Р	SF	Installation record	Y	2018	Visual insp during install or repair	Installed after lead ban	N
2131 DRAGON CT	N	Р	N	1"	2018	Р	SF	Installation record	Υ	2018	Visual insp during install or repair	Installed after lead ban	N
2133 DRAGON CT	N	Р	N	1"	2018	Р	SF	Installation record	Υ	2018	Visual insp during install or repair	Installed after lead ban	N
2137 DRAGON CT	N	P	N	1"	2018	P	SF	Installation record	Υ	2018	Visual insp during install or repair	Installed after lead ban	N
1899 WIZARD WY	N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1903 WIZARD WY	N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1907 WIZARD WY	N	P	N	1"	2019	P	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2147 SEEKER LN 2149 SEEKER LN	N N	P	N	1"	2019	P	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
		Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N

2151 SEEKER LN       N         2153 SEEKER LN       N         2155 SEEKER LN       N         2157 SEEKER LN       N         2005 DOBBY ST       N         2154 SEEKER LN       N         2152 SEEKER LN       N         2150 SEEKER LN       N         2148 SEEKER LN       N         2146 SEEKER LN       N         1902 WIZARD DR       N	P P P P P P P P	N N N N	1" 1" 1" 1"	2019 2019 2019 2019	P P P	SF SF SF	Installation record Installation record Installation record	Y Y Y	2019 2019 2019	Visual insp during install or repair Visual insp during install or repair Visual insp during install or repair	Installed after lead ban Installed after lead ban Installed after lead ban	N N N
2155 SEEKER LN       N         2157 SEEKER LN       N         2005 DOBBY ST       N         2154 SEEKER LN       N         2152 SEEKER LN       N         2150 SEEKER LN       N         2148 SEEKER LN       N         2146 SEEKER LN       N	P P P P P	N N N	1" 1"	2019	P	SF		'	2019			
2157 SEEKER LN       N         2005 DOBBY ST       N         2154 SEEKER LN       N         2152 SEEKER LN       N         2150 SEEKER LN       N         2148 SEEKER LN       N         2146 SEEKER LN       N	P P P P	N N	1"		'		Installation record	'		Visual insp during install or repair	Installed after lead ban	N
2005 DOBBY ST       N         2154 SEEKER LN       N         2152 SEEKER LN       N         2150 SEEKER LN       N         2148 SEEKER LN       N         2146 SEEKER LN       N	P P P	N		2019	n							
2154 SEEKER LN       N         2152 SEEKER LN       N         2150 SEEKER LN       N         2148 SEEKER LN       N         2146 SEEKER LN       N	P P P		1"		Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2152 SEEKER LN       N         2150 SEEKER LN       N         2148 SEEKER LN       N         2146 SEEKER LN       N	P P	N		2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2150 SEEKER LN       N         2148 SEEKER LN       N         2146 SEEKER LN       N	P		1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2148 SEEKER LN N 2146 SEEKER LN N	•	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2146 SEEKER LN N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
		N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1902 WIZARD DR N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1898 WIZARD WY N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1894 WIZARD WY N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1890 WIZARD WY N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1886 WIZARD WY N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
927 RAVEN CLAW CT N	Р	N	1"	2018	Р	SF	Installation record	Υ	2018	Visual insp during install or repair	Installed after lead ban	N
929 RAVEN CLAW CT N	Р	N	1"	2018	Р	SF	Installation record	Υ	2018	Visual insp during install or repair	Installed after lead ban	N
931 RAVEN CLAW CT N	Р	N	1"	2018	Р	SF	Installation record	Υ	2018	Visual insp during install or repair	Installed after lead ban	N
932 RAVEN CLAW CT N	Р	N	1"	2018	Р	SF	Installation record	Υ	2018	Visual insp during install or repair	Installed after lead ban	N
934 RAVEN CLAW CT N	Р	N	1"	2018	Р	SF	Installation record	Υ	2018	Visual insp during install or repair	Installed after lead ban	N
930 RAVEN CLAW CT N	Р	N	1"	2018	Р	SF	Installation record	Υ	2018	Visual insp during install or repair	Installed after lead ban	N
926 RAVEN CLAW CT N	P	N	1"	2018	P	SF	Installation record	Y	2018	Visual insp during install or repair	Installed after lead ban	N
2244 CREEKSEDGE WAY N	P	N	1"	2019	<u>.</u> Р	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2238 CREEKSEDGE WAY N	' P	N	1"	2019	P	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2224 CREEKSEDGE CIRCLE N	P	N	1"	2019	<u>.</u> Р	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2218 CREEKSEDGE CIRCLE N	' P	N	1"	2019	P	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2212 CREEKSEDGE CIRCLE N	P	N	1"	2019	P	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2206 CREEKSEDGE CIRCLE N	' P	N	1"	2019	P	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2200 CREEKSEDGE CIRCLE N	P P	N	1"	2019	D	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2194 CREEKSEDGE CIRCLE N	P	N	1"	2019	P	SF	Installation record		2019	Visual insp during install or repair	Installed after lead ban	N
2188 CREEKSEDGE CIRCLE N	P	N	1"	2019	D	SF	Installation record	V	2019	Visual insp during install or repair	Installed after lead ban	N
2189 CREEKSEDGE CIRCLE N	P P	N	1"	2019	P P	SF	Installation record		2019	Visual insp during install or repair	Installed after lead ban	N
2195 CREEKSEDGE CIRCLE N	P P	N	1"	2019	P D	SF		Y	2019			N
2207 CREEKSEDGE CIRCLE N	P	N N	1"	2019	<u>Р</u>	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
	P P		1"		<u>Р</u>		Installation record	•		Visual insp during install or repair	Installed after lead ban	
2209 CREEKSEDGE CIRCLE N	<u> </u>	N N		2019	<u>'</u>	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2215 CREEKSEDGE CIRCLE N	P	N N	1"	2019	P	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2221 CREEKSEDGE CIRCLE N	P	N	1"	2019	P	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2227 CREEKSEDGE CIRCLE N	P	N	1"	2019	P	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2231 CREEKSEDGE CIRCLE N	P	N	1"	2019	P	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2235 CREEKSEDGE CIRCLE N	Р	N	1"	2019	Р	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2239 CREEKSEDGE CIRCLE N	Р	N	1"	2019	P	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2241 CREEKSEDGE CIRCLE N	Р	N	1"	2019	Р	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2243 CREEKSEDGE CIRCLE N	P	N	1"	2019	Р	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2233 CREEKSEDGE CIRCLE N	Р	N	1"	2019	Р	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2229 CREEKSEDGE CIRCLE N	P	N	1"	2019	Р	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2223 CREEKSEDGE CIRCLE N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2217 CREEKSEDGE CI N	Р	N	1"	2019	Р	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2211 CREEKSEDGE CIRCLE N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2203 CREEKSEDGE CIRCLE N	Р	N	1"	2019	Р	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2204 CREEKSEDGE CIRCLE N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2210 CREEKSEDGE CIRCLE N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2216 CREEKSEDGE CIRCLE N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2222 CREEKSEDGE CIRCLE N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2228 CREEKSEDGE CIRCLE N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2703 LAWRENCE DR N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2709 LAWRENCE DR N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2715 LAWRENCE DR N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2900 SABAL OAK DR N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2800 TAMBOUR TRL N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2802 TAMBOUR TRL N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2812 TAMBOUR TRL N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2818 TAMBOUR TRL N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2824 TAMBOUR TRL N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2830 TAMBOUR TRL N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2840 TAMBOUR TRL N	P	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2937 SABAL OAK DR N	P	N	1"	2019	P	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2939 SABAL OAK DR N	P	N	1"	2019	P	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2925-2927 SABAL OAK DR FORT HOWARD HOMES N	P	N	1"	2019	P	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2927 SABAL OAK DR FORT HOWARD HOMES N	P	N	1"	2019	<u>.</u> Р	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2919 SABAL OAK DR N	P	N	1"	2019	P	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2921 SABAL OAK DR N	P	N	1"	2019	<u>.</u> Р	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
2911 SABAL OAK DR N	' P	N	1"	2019	P	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
	•	.,	-	_013	•			•	_013	Tional map during motali of Tepuli		.,

2015 ASABLO CANCER   N   P   N   1"   2019   P   55   Installation encord   Y   2019   Visual ingo during install or repair installed after lead to 2016 ASABLE O ANCER   N   P   N   1"   2019   P   55   Installation record   Y   2019   Visual ingo during install or repair installed after lead to 2016 ASABLE O ANCER   N   P   N   1"   2019   P   55   Installation record   Y   2019   Visual ingo during install or repair installated after lead to 2016 ASABLE O ANCER   N   P   N   1"   2019   P   55   Installation record   Y   2019   Visual ingo during install or repair installated after lead to 2016 ASABLE O ANCER   N   P   N   1"   2019   P   55   Installation record   Y   2019   Visual ingo during install or repair installated after lead to 2016 ASABLE O ANCER   N   P   N   1"   2019   P   55   Installation record   Y   2019   Visual ingo during install or repair installated after lead to 2016 ASABLE O ANCER   N   P   N   1"   2019   P   55   Installation record   Y   2019   Visual ingo during install or repair installated after lead to 2016 ASABLE O ANCER   N   P   N   1"   2019   P   55   Installation record   Y   2019   Visual ingo during install or repair installated after lead to 2016 ASABLE O ANCER   N   P   N   1"   2019   P   55   Installation record   Y   2019   Visual ingo during install or repair installated after lead to 2016 ASABLE O ANCER   N   P   N   1"   2019   P   55   Installation record   Y   2019   Visual ingo during install or repair installated after lead to 2016 ASABLE O ANCER   N   P   N   1"   2019   P   55   Installation record   Y   2019   Visual ingo during install or repair installated after lead to 2016 ASABLE O ANCER   N   P   N   1"   2019   P   55   Installation record   Y   2019   Visual ingo during install or repair installated after lead to 2016 ASABLE O ANCER   N   P   N   1"   2019   P   55   Installation record   Y   2019   Visual ingo during install or repair installated after lead to 2016 ASABLE O ANCER   N   P   N   1"   2019   P   55   Installation record   Y   2019	N N N N N N N N N N N N N N N N N N N
2918 SABLO MX PR	N N N N N N N N N N N N N N N N N N N
2923 SABAL OMX DR	N N N N N N N N N N N N N N N N N N N
280 SABAL OAK DR  N P N 12 2019 P SF Installation record Y 2019 Visual insp during install or repair Installat Affer lead 284 SABAL OAK DR  N P N 12 2019 P SF Installation record Y 2019 Visual insp during install or repair Installated Affer lead 284 SABAL OAK DR  N P N 12 2019 P SF Installation record Y 2019 Visual insp during install or repair Installated Affer lead 284 SABAL OAK DR  R N P N 12 2019 P SF Installation record Y 2019 Visual insp during install or repair Installated Affer lead 284 TAMBOUR TRI.  2841 TAMBOUR TRI.  N P N 12 2019 P SF Installation record Y 2019 Visual insp during install or repair Installated Affer lead 284 TAMBOUR TRI.  2841 TAMBOUR TRI.  N P N 12 2019 P SF Installation record Y 2019 Visual insp during install or repair Installated Affer lead 284 TAMBOUR TRI.  N P N 12 2019 P SF Installation record Y 2019 Visual insp during install or repair Installated Affer lead 284 TAMBOUR TRI.  N P N 12 2019 P SF Installation record Y 2019 Visual insp during install or repair Installated Affer lead 284 TAMBOUR TRI.  N P N 12 2019 P SF Installation record Y 2019 Visual insp during install or repair Installated Affer lead 284 TAMBOUR TRI.  N P N 12 2019 P SF Installation record Y 2019 Visual insp during install or repair Installated Affer lead 284 TAMBOUR TRI.  N P N 12 2019 P SF Installation record Y 2019 Visual insp during install or repair Installated Affer lead 284 TAMBOUR TRI.  N P N 12 2019 P SF Installation record Y 2019 Visual insp during install or repair Installated Affer lead 284 TAMBOUR TRI.  N P N 12 2019 P SF Installation record Y 2019 Visual insp during install or repair Installated Affer lead 284 TAMBOUR TRI.  N P N 12 2019 P SF Installation record Y 2019 Visual insp during install or repair Installated Affer lead 284 TAMBOUR TRI.  N P N 12 2019 P SF Installation record Y 2019 Visual insp during install or repair Installated Affer lead 284 TAMBOUR TRI.  N P N 12 2018 P SF Installation record Y 2019 Visual insp during install or repair Installated Affer lead 284 TAMBOUR TRI.  N P N	N N N N N N N N N N N N N N N N N N N
2842 SABAL CAK DR N P N 1 2019 P SF Installation record Y 2019 Visual insign during install of repair Installed after lead the lead after lead to separate the separate should be separate the separate should be separate the separate should be	N N N N N N N N N N N N N N N N N N N
2845 RABAL OAK DR  N P N 1 2019 P SF Installation record V 2019 Visual insp during install or repair Installed after lead to the control of t	N N N N N N N N N N N N N N N N N N N
2841 TAMBOUR TEL	N N N N N N N N N N N N N N N N N N N
284 TAMBOUR TRL  N P N 1" 2019 P 5F Installation record Y 2019 Visual ing during install or repair Installed after lead to 283 TAMBOUR TRL  N P N 1" 2019 P 5F Installation record Y 2019 Visual ing during install or repair Installed after lead to 283 TAMBOUR TRAL  N P N 1" 2019 P 5F Installation record Y 2019 Visual ing during install or repair Installed after lead to 283 TAMBOUR TRAL  N P N 1" 2019 P 5F Installation record Y 2019 Visual ings during install or repair Installed after lead to 283 TAMBOUR TRAL  N P N 1" 2019 P 5F Installation record Y 2019 Visual ings during install or repair Installed after lead to 283 TAMBOUR TRAL  N P N 1" 2019 P 5F Installation record Y 2019 Visual ings during install or repair Installed after lead to 283 TAMBOUR TRAL  N P N 1" 2019 P 5F Installation record Y 2019 Visual ings during install or repair Installed after lead to 283 TAMBOUR TRAL  N P N 1" 2019 P 5F Installation record Y 2019 Visual ings during install or repair Installed after lead to 283 TAMBOUR TRAL  N P N 1" 2019 P 5F Installation record Y 2019 Visual ings during install or repair Installed after lead to 283 TAMBOUR TRAL  N P N 1" 2019 P 5F Installation record Y 2019 Visual ings during install or repair Installed after lead to 283 TAMBOUR TRAL  N P N 1" 2019 P 5F Installation record Y 2019 Visual ings during install or repair Installed after lead to 283 TAMBOUR TRAL  N P N 1" 2018 P 5F Installation record Y 2019 Visual ings during install or repair Installed after lead to 283 TAMBOUR TRAL  N P N 1" 2018 P 5F Installation record Y 2019 Visual ings during install or repair Installed after lead to 283 TAMBOUR TRAL  N P N 1" 2018 P 5F Installation record Y 2018 Visual ings during install or repair Installed after lead to 283 TAMBOUR TRAL  N P N 1" 2018 P 5F Installation record Y 2018 Visual ings during install or repair Installed after lead to 283 TAMBOUR TRAL  N P N 1" 2018 P 5F Installation record Y 2018 Visual ings during install or repair Installed after lead to 283 TAMBOUR TRAL  N P N 1" 2018 P 5F Installation r	N N N N N N N N N N N N N N N N N N N
2835 TAMBOUR TRIL  N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead t 2825 TAMBOUR TRIL  N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead t 2825 TAMBOUR TRIL  N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead t 2819 TAMBOUR TRIL  N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead t 2819 TAMBOUR TRIL  N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead t 2825 TAMBOUR TRIL  N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead t 2825 TAMBOUR TRIL  N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead t 2825 TAMBOUR TRIL  N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead t 2825 TAMBOUR TRIL  N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead t 2825 TAMBOUR TRIL  N P N 1" 2018 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead t 2825 TAMBOUR TRIL  N P N 1" 2018 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead t 2825 TAMBOUR TRIL  N P N 1" 2018 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead t 2825 TAMBOUR TRIL  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead t 1825 TAMBOUR TRIL  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead t 1825 TAMBOUR TRIL  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead t 1825 TAMBOUR TRIL  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead t 1825 TAMBOUR TRIL  N P N 1" 2018 P SF Installa	N N N N N N N N N N N N N N N N N N N
2831 TAMBOUR TRAL  N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to 2831 TAMBOUR TRL  N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to 2803 TAMBOUR TRL  N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to 2803 TAMBOUR TRL  N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to 2803 TAMBOUR TRL  N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to 2803 TAMBOUR TRL  N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to 2803 TAMBOUR TRL  N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to 2803 TAMBOUR TRL  N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to 2803 TAMBOUR TRL  N P N 1" 2018 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to 2803 TAMBOUR TRL  N P N 1" 2018 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to 2803 TAMBOUR TRL  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2803 TAMBOUR TRL  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2803 TAMBOUR TRL  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2803 TAMBOUR TRL  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2803 TAMBOUR TRL  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2803 TAMBOUR TRL  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2803 TAMBOUR TRL  N P N 1" 2018 P SF Installa	N N N N N N N N N N N N N N N N N N N
2825 TAMBOUR TRL	N N N N N N N N N N N N N N N N N N N
2819 TAMBOUR TRL	N N N N N N N N N N N N N N N N N N N
2013 AMBOUR TRL   N	N N N N N N N N N N N N N N N N N N N
714 TAMBOUR TRL	N N N N N N N N N N N N N N N N N N N
722 TAMBOUR CT  N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to 2951 - 2981 SABAL OAK DR TIM HALBROOK BUILDERS N P N P N 1" 2018 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to 2951 - 2981 SABAL OAK DR TIM HALBROOK BUILDERS N P N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2951 - 2951 SABAL OAK DR TIM HALBROOK BUILDERS N P N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2952 SABAL OAK DR TIM HALBROOK BUILDERS N P N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2952 SABAL OAK DR TIM HALBROOK BUILDERS N P N P N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2952 SABAL OAK DR TIM HALBROOK BUILDERS N P N P N P N P N P N P N P N P N P N	N N N N N N N N N N
2951 - 2981 SABAL OAK DR TIM HALBROOK BUILDERS N P N 4" 2019 P MF Installation record Y 2019 Visual insp during install or repair Installed after lead to 2003 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2019 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 1999 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 1999 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2000 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2000 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2000 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2004 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2004 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2004 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2006 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2006 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2006 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2008 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2008 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2008 DOBBY ST Installation record Y 2018 Visual insp during install or repair	N N N N N N N N N N N N N N N N N N N
2003 DOBBY ST  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 1999 DOBBY ST  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2002 DOBBY ST  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2002 DOBBY ST  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2004 DOBBY ST  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2004 DOBBY ST  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2004 DOBBY ST  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2006 DOBBY ST  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2008 DOBBY ST  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN STALLED TO 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN STALLED TO 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN STALLED TO 2018 Visual insp during install or repair Installed after lead to 2018 Visual insp during install or repair Installed after le	N N N N N N N N
2003 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2001 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 1999 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2002 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2002 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2004 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2004 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2004 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2004 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2008 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installe	N N N N N N N N N N N N N N N N N N N
2001 DOBBY ST  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 1997 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 2000 DOBBY ST N P N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 2000 DOBBY ST N P N P N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 2002 DOBBY ST N P N P N P N P N P N P N P N P N P N	N N N N N N N N N N N N N N N N N N N
1999 DOBBY ST  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST N P N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST Installation record Y 2018 Visual insp during install or repair Installed after lead to 1997 DOBBY ST Installation record Y 2018 Visua	N N N N N
1997 DOBBY ST  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2000 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2002 DOBBY ST N P N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2002 DOBBY ST N P N P N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2004 DOBBY ST N P N P N P N P N P N P N P N P N P N	N N N N N
2000 DOBBY ST  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by the stall of	N N N N N
2002 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2004 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2006 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2006 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2008 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN N P N N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2009 GOBLET LN N P N N N N N N N N N N N N N N N N	N N N N
2004 DOBBY ST  N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by the stall of the plant of	N N N
2006 DOBBY ST 2008 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by the stalled a	N N N
2008 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2209 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2019 GOBLET LN P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2019 GOBLET LN P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2019 GOBLET LN P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2019 GOBLET LN P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2019 GOBLET LN P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2019 GOBLET LN P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2019 GOBLET LN P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2019 GOBLET LN P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2019 GOBLET LN P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2019 GOBLET LN P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to 2019 GOBLET LN P SF Installation record Y 2019 GOBLET LN P SF Installation record Y 2019 GOBLET LN P SF Installation record	N N
2209 GOBLET LN  N  P  N  I"  2018  P  SF  Installation record  Y  2018  Visual insp during install or repair  Installed after lead to specified by the specifie	N
955 ELDER WAND CT N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by the stalled after lead	
953 ELDER WAND CT N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 954 ELDER WAND N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 954 ELDER WAND N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 954 ELDER WAND N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 954 ELDER WAND	N
951 ELDER WAND CT N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 10 SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 10 SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 10 SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 10 SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 10 SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 10 SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 10 SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 10 SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 10 SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 10 SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 10 SF Installation record Y 2018 Visual insp during install or repair Installed after lead by 10 SF Installation record Y 2018 Visual insp during install Or repair Installed after lead by 10 SF Installation record Y 2018 Visual insp during install Or repair Installed after lead by 10 SF Installation record Y 2018 Visual insp during install Or repair Installation record Y 2018 Visual insp during install Or repair Installation record Y 2018 Visual insp during install Or repair Installation record Y 2018 Visual insp during install Or repair Installation record Y 2018 Visual insp during install Or repair Installation record Y 2018 Visual insp during install Or repair Installation record Y 2018 Visual insp during install Or repair Installation record Y 2018 Visual insp during installation re	N
954 ELDER WAND N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to	
	N
2202 GOBLET LIN N P IN 1 2018 P SF INStallation record f 2018 Visual inspiral installed after lead to	
2204 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by	
	N N
2208 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by the control of the	N
2212 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by the control of the	
2216 GOBLET LANE N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to	N N
2220 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by the second of the se	
2226 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by the second of the se	N N
1971 WIZARD WY N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead by	
1965 WIZARD WAY N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead by	N
1957 WIZARD WAY N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by	
2028 DOBBY STREET N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to	
2213 GOBLET LANE N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by	N
2217 GOBLET LN N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by	N
2020 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by	N
2016 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead by	N
2012 DOBBY ST N P N 1" 2018 P SF Installation record Y 2018 Visual insp during install or repair Installed after lead to	N
1946 WIZARD WAY N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to	N
1942 WIZARD WAY N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to	N
1936 WIZARD WAY N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead b	N
1932 WIZARD WAY N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead by	N
1928 WIZARD WAY N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead by	N
1922 WIZARD WAY N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead by	N
2143 SEEKER LANE N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead by	N
1911 WIZARD WAY N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead by	N
1915 WIZARD WAY N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to	N
1921 WIZARD WAY N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to	N
1925 WIZARD WAY N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to	N
1929 WIZARD WAY N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to	N
1933 WIZARD WAY N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to	N
1937 WIZARD WAY N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to	N
1941 WIZARD WAY N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead to	N
1945 WIZARD WAY N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead by	N
1667 TORCHWOOD TRL N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead by	N
1663 TORCHWOOD TRL N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead by	
1648 TORCHWOOD TRL N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead by	N
1656 TORCHWOOD TRL N P N 1" 2019 P SF Installation record Y 2019 Visual insp during install or repair Installed after lead by	
1660 TORCHWOOD TRAIL  N P N 1" 2019 P SF Installation record Y 2019 Visual inspiduring install or repair Installed after lead by the stall of the st	
1664 TORCHWOOD TRL N P N 1" 2019 P SF Installation record Y 2019 Visual inspiduling install or repair Installed after lead by the control of	
1668 TORCHWOOD TRL N P N 1" 2019 P SF Installation record Y 2019 Visual inspiration or repair Installed after lead by the control of the cont	N
2389 TIGERWOOD TRL  N P N 1" 2019 P SF Installation record Y 2019 Visual inspiduling install or repair Installed after lead to	
	11

2385 TIGERWOOD TRL		N	P	N	1"	2019	P	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
1571 ECHO PINE CT		N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1565 ECHO PINE CT		N	Р	N	1"	2019	P	SF	Installation record	Y	2019	Visual insp during install or repair	Installed after lead ban	N
1557 ECHO PINE CT		N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1553 ECHO PINE CT		N	Р	N	1"	2019	P	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1560 ECHO PINE CT		N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1564 ECHO PINE CT		N	Р	N	1"	2019	P	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1572 ECHO PINE CT		N	Р	N	1"	2019	P	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2371 TIGERWOOD TRL		N	Р	N	1"	2019	P	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1469 CHICKORY CT		N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1465 CHICKORY CT		N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1451 CHICKORY CT		N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1449 CHICKORY CT		N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1450 CHICKORY CT		N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1452 CHICKORY CT		N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1454 CHICKORY CT		N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1456 CHICKORY CT		N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
1462 CHICKORY CT		N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2359 TIGERWOOD TRL		N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2355 TIGERWOOD TRL		N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2351 TIGERWOOD TRL		N	P	N	1"	2019	P	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2347 TIGERWOOD TRL		N	Р	N	1"	2019	Р	SF	Installation record	Υ	2019	Visual insp during install or repair	Installed after lead ban	N
2350 LAWRENCE PARKWAY	ISA BUILDING LLC	N	P	N	8"	2020	P	NONRES	Installation record	Υ	2020	Visual insp during install or repair	Installed after lead ban	N
2812 AMERICAN BLVD	FELTS LLC	N	P	N	8"	2022	P	NONRES	Installation record	Y	2022	Visual insp during install or repair	Installed after lead ban	N
2140 LITTLE RAPIDS RD	TRINKS INC	N	P	N	8"	2021	P	NONRES	Installation record	Y	2021	Visual insp during install or repair	Installed after lead ban	N
2168 POTTER DR	THINKS INC	N	P	N	1"	2021	P	SF	Installation record	Υ Υ	2021	Visual insp during install or repair	Installed after lead ban	N
2166 POTTER DR		N	D	N	1"	2021	D	SF	Installation record	· v	2021	Visual insp during install or repair	Installed after lead ban	N
2162 POTTER DR		N	P	N	1"	2021	P	SF	Installation record	Y	2021	Visual insp during install or repair	Installed after lead ban	N
2160 POTTER DR		N	P	N	1"	2021	P	SF	Installation record	· Y	2021	Visual insp during install or repair	Installed after lead ban	N
2158 POTTER DR		N N	P	N N	1"	2021	P P	SF	Installation record	Y	2021	Visual insp during install or repair	Installed after lead ban	N
2155 POTTER DR		N N	P D	N N	1"	2021	P D	SF		Y Y	2021			N
2157 POTTER DR		N N	P	N N	1"	2021	P P	SF	Installation record	Y	2021	Visual insp during install or repair	Installed after lead ban	N
		N N	P P	***			<u>Р</u>		Installation record	Y Y		Visual insp during install or repair	Installed after lead ban	
2159 POTTER DR			Р Р	N	1"	2021		SF	Installation record		2021	Visual insp during install or repair	Installed after lead ban	N
2161 POTTER DR		N	<u> </u>	N	1"	2021	Р	SF	Installation record	Y	2021	Visual insp during install or repair	Installed after lead ban	N
2165 POTTER DR		N	P	N	1"	2021	P	SF	Installation record	Y	2021	Visual insp during install or repair	Installed after lead ban	N
2167 POTTER DR		N	P	N	1"	2021	P	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
2171 POTTER DR		N	P	N	1"	2021	P	SF	Installation record	Y	2021	Visual insp during install or repair	Installed after lead ban	N
914 HEDWIG CT		N	Р	N	1"	2021	Р	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
906 HEDWIG CT		N	P	N	1"	2021	P	SF	Installation record	Y	2021	Visual insp during install or repair	Installed after lead ban	N
905 HEDWIG CT		N	Р	N	1"	2021	Р	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
909 HEDWIG CT		N	P	N	1"	2021	P	SF	Installation record	Y	2021	Visual insp during install or repair	Installed after lead ban	N
917 HEDWIG CT		N	Р	N	1"	2021	Р	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
921 HEDWIG CT		N	Р	N	1"	2021	P	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
925 HEDWIG CT		N	Р	N	1"	2021	Р	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
2318 GRINGOTTS WAY		N	Р	N	1"	2021	P	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
2317 GRINOTTS WAY		N	Р	N	1"	2021	Р	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
2403 RIDDLE CT		N	Р	N	1"	2021	P	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
2409 RIDDLE CT		N	Р	N	1"	2021	Р	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
2415 RIDDLE CT		N	Р	N	1"	2021	Р	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
2421 RIDDLE CT		N	Р	N	1"	2021	Р	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
2427 RIDDLE CT		N	Р	N	1"	2021	Р	SF	Installation record	Y	2021	Visual insp during install or repair	Installed after lead ban	N
2439 RIDDLE CT		N	Р	N	1"	2021	Р	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
2445 RIDDLE CT		N	Р	N	1"	2021	P	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
2454 RIDDLE COURT		N	Р	N	1"	2021	Р	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
2442 RIDDLE CT		N	Р	N	1"	2021	Р	SF	Installation record	Y	2021	Visual insp during install or repair	Installed after lead ban	N
2436 RIDDLE CT		N	Р	N	1"	2021	Р	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
2430 RIDDLE CT		N	Р	N	1"	2021	Р	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
2424 RIDDLE CT		N	Р	N	1"	2021	Р	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
2418 RIDDLE CT		N	P	N	1"	2021	P	SF	Installation record	Y	2021	Visual insp during install or repair	Installed after lead ban	N
2412 RIDDLE CT		N	P	N	1"	2021	P	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
2406 RIDDLE CT		N	P	N	1"	2021	P	SF	Installation record	Υ	2021	Visual insp during install or repair	Installed after lead ban	N
2400 RIDDLE CT		N	P	N	1"	2021	Р	SF	Installation record	Y	2021	Visual insp during install or repair	Installed after lead ban	N
1164 APPLEWOOD DR		N N	P	N	1"	2022	<u>.</u> Р	SF	Installation record	Y	2022	Visual insp during install or repair	Installed after lead ban	N
1170 APPLEWOOD DR		N	P	N	1"	2022	P	SF	Installation record	Υ Υ	2022	Visual insp during install or repair	Installed after lead ban	N
1176 APPLEWOOD DR		N	P	N	1"	2022	P	SF	Installation record	Y	2022	Visual insp during install or repair	Installed after lead ban	N
1065 NUTMEG		N N	P	N	1"	2022	P	SF	Installation record	Y	2022	Visual insp during install or repair	Installed after lead ban	N
1061 NUTMEG DR		N N	P D	N	1"	2022	P P	SF	Installation record	Y	2022	Visual insp during install or repair	Installed after lead ban	N
1057 NUTMEG DR		N N	P	N N	1"	2022	P	SF	Installation record	V	2022	Visual insp during install or repair  Visual insp during install or repair	Installed after lead ban	N
1057 NOTMEG DR 1053 NUTMEG DR		N N	P P	N N	1"	2022	<u>Р</u>	SF		Y	2022			
		N N	<u>Р</u>				P P		Installation record	Y Y		Visual insp during install or repair	Installed after lead ban	N
1051 NUTMEG DR			P P	N	1"	2022	P P	SF	Installation record	Y Y	2022	Visual insp during install or repair	Installed after lead ban	N
1050 NUTMEG DR		N		N	1"	2022		SF	Installation record		2022	Visual insp during install or repair	Installed after lead ban	N
1054 NUTMEG DR		N	Р	N	1"	2022	Р	SF	Installation record	Y	2022	Visual insp during install or repair	Installed after lead ban	N

1058 NUTMEG DR		N	Р	N	1"	2022	Р	SF	Installation record	Υ	2022	Visual insp during install or repair	Installed after lead ban	N
1062 NUTMEG DR		N	Р	N	1"	2022	Р	SF	Installation record	Υ	2022	Visual insp during install or repair	Installed after lead ban	N
1066 NUTMEG DR		N	Р	N	1"	2022	Р	SF	Installation record	Υ	2022	Visual insp during install or repair	Installed after lead ban	N
1070 NUTMEG DR		N	Р	N	1"	2022	Р	SF	Installation record	Υ	2022	Visual insp during install or repair	Installed after lead ban	N
1074 NUTMEG DR		N	Р	N	1"	2022	Р	SF	Installation record	Υ	2022	Visual insp during install or repair	Installed after lead ban	N
1181 APPLEWOOD DR		N	Р	N	1"	2022	Р	SF	Installation record	Υ	2022	Visual insp during install or repair	Installed after lead ban	N
1163 APPLEWOOD DR		N	Р	N	1"	2022	Р	SF	Installation record	Υ	2022	Visual insp during install or repair	Installed after lead ban	N
1159 APPLEWOOD DR		N	Р	N	1"	2022	Р	SF	Installation record	Υ	2022	Visual insp during install or repair	Installed after lead ban	N
1157 APPLEWOOD DR		N	Р	N	1"	2022	Р	SF	Installation record	Υ	2022	Visual insp during install or repair	Installed after lead ban	N
1153 APPLEWOOD DR		N	Р	N	1"	2022	Р	SF	Installation record	Υ	2022	Visual insp during install or repair	Installed after lead ban	N
1091 NUTMEG DR		N	Р	N	1"	2022	Р	SF	Installation record	Υ	2022	Visual insp during install or repair	Installed after lead ban	N
1095 NUTMEG DR		N	Р	N	1"	2022	Р	SF	Installation record	Υ	2022	Visual insp during install or repair	Installed after lead ban	N
1098 NUTMEG DR		N	Р	N	1"	2022	Р	SF	Installation record	Υ	2022	Visual insp during install or repair	Installed after lead ban	N
1085 NUTMEG DR		N	Р	N	1"	2022	Р	SF	Installation record	Υ	2022	Visual insp during install or repair	Installed after lead ban	N
1263 AUTUMN FIELD LN		N	Р	N	1"	2023	Р	SF	Installation record	Υ	2023	Visual insp during install or repair	Installed after lead ban	N
1265 AUTUMN FIELD LN		N	Р	N	1"	2023	Р	SF	Installation record	Υ	2023	Visual insp during install or repair	Installed after lead ban	N
1267 AUTUMN FIELD LN		N	Р	N	1"	2023	Р	SF	Installation record	Υ	2023	Visual insp during install or repair	Installed after lead ban	N
1260 AUTUMN FIELD LN		N	Р	N	1"	2023	Р	SF	Installation record	Υ	2023	Visual insp during install or repair	Installed after lead ban	N
2679 ANDROMEDA DR		N	Р	N	1"	2015	Р	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
2675 ANDROMEDA DR		N	Р	N	1"	2015	Р	SF	Installation record	Υ	2015	Visual insp during install or repair	Installed after lead ban	N
2400 SHADY CT	INTERNAL ACCOUNT	N	Р	N	1"	2020	Р	NONRES	Installation record	Υ	2020	Visual insp during install or repair	Installed after lead ban	N